OIL ANALYSIS REPORT

Sample Rating Trend



NORMAL

Area
[BOSTON]
Machine Id
ALSTOM R148
Component
Gearbox
Fluid
TOTAL CARTER SH 220 (3 GAL)

DIAGNOSIS

Recommendation
Resample at the next service interval to monitor.

Wear
All component wear rates are normal.

Contamination
There is no indication of any contamination in the oil.

Fluid Condition
The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**WC0781623**	WC0667687	WCM2295653
Sample Date		Client Info		**10 Nov 2023**	17 May 2023	01 Feb 2019
Machine Age	hrs	Client Info		**0**	0	0
Oil Age	hrs	Client Info		**0**	0	0
Oil Changed		Client Info		**N/A**	N/A	N/A
Sample Status				**NORMAL**	NORMAL	NORMAL

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	**103**	190	116
Chromium	ppm	ASTM D5185m	>10	**<1**	2	1
Nickel	ppm	ASTM D5185m	>10	**<1**	<1	<1
Titanium	ppm	ASTM D5185m		**0**	<1	<1
Silver	ppm	ASTM D5185m		**0**	0	0
Aluminum	ppm	ASTM D5185m	>25	**1**	2	2
Lead	ppm	ASTM D5185m	>50	**2**	2	2
Copper	ppm	ASTM D5185m	>200	**28**	40	65
Tin	ppm	ASTM D5185m	>10	**<1**	0	0
Antimony	ppm	ASTM D5185m	>5	**---**	---	0
Vanadium	ppm	ASTM D5185m		**0**	0	0
Cadmium	ppm	ASTM D5185m		**0**	0	0

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		**<1**	4	2
Barium	ppm	ASTM D5185m		**0**	0	0
Molybdenum	ppm	ASTM D5185m		**0**	<1	<1
Manganese	ppm	ASTM D5185m		**2**	2	2
Magnesium	ppm	ASTM D5185m		**<1**	3	0
Calcium	ppm	ASTM D5185m		**10**	16	7
Phosphorus	ppm	ASTM D5185m		**337**	362	219
Zinc	ppm	ASTM D5185m		**84**	72	56
Sulfur	ppm	ASTM D5185m		**3386**	4054	2930

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	**17**	36	14
Sodium	ppm	ASTM D5185m		**38**	44	34
Potassium	ppm	ASTM D5185m	>20	**0**	2	0

FLUID DEGRADATION		method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		**0.28**	0.50	0.399

VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	**NONE**	LIGHT	LIGHT
Yellow Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Precipitate	scalar	*Visual	NONE	**NONE**	NONE	NONE
Silt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Debris	scalar	*Visual	NONE	**NONE**	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Appearance	scalar	*Visual	NORML	**NORML**	NORML	NORML
Odor	scalar	*Visual	NORML	**NORML**	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	**NEG**	NEG	NEG
Free Water	scalar	*Visual		**NEG**	NEG	NEG

OIL ANALYSIS REPORT





FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445		**232**	226	223.6

SAMPLE IMAGES	method	limit/base	current	history1	history2
Color			*no image*	*no image*	*no image*
Bottom			*no image*	*no image*	*no image*

GRAPHS

















Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : WC0781623
Lab Number : 06011052
Unique Number : 10750196
Test Package : MOB 2

Received : 17 Nov 2023
Diagnosed : 20 Nov 2023
Diagnostician : Wes Davis

To discuss this sample report, contact Customer Service at 1-800-237-1369.
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

AMTRAK
1401 W STREET NE, HIGH SPEED RAIL 2ND FLOOR
WASHINGTON, DC
US 20018
Contact: MICHAEL PORTER
michael.porter@amtrak.com
T: (202)870-1399
F: