PROBLEM SUMMARY

Sample Rating Trend



WATER

Machine Id
KAESER SM 7.5 8105335 (S/N 1213)
Component
Compressor
Fluid
KAESER SIGMA (OEM) S-460 (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

We recommend you service the filters on this component. We were unable to perform a particle count due to a high concentration of particles present in this sample. We advise that you stop the unit and follow the water drain-off procedure for this component. We recommend an early resample in 500 hours to monitor this condition.

PROBLEMATIC TEST RESULTS

Sample Status				**ABNORMAL**	ABNORMAL	ABNORMAL
Water	%	ASTM D6304	>0.05	▲ **0.077**	▲ 0.120	0.018
ppm Water	ppm	ASTM D6304	>500	▲ **770**	▲ 1200	185.4
Debris	scalar	*Visual	NONE	▲ **HEAVY**	NONE	NONE

Customer Id: QUADUN
Sample No.: KCPA009796
Lab Number: 06016397
Test Package: IND 2

To manage this report scan the QR code

To discuss the diagnosis or test data:
Jonathan Hester +1 919-379-4092 x4092
jhester@wearcheckusa.com

To change component or sample information:
Customer Service +1 1-800-237-1369
customerservice@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Filter	---	---	?	We recommend you service the filters on this component.
Alert	---	---	?	We were unable to perform a particle count due to a high concentration of particles present in this sample.

HISTORICAL DIAGNOSIS

28 May 2023 Diag: Jonathan Hester

WATER

The filter change at the time of sampling has been noted. We were unable to perform a particle count due to a high concentration of particles present in this sample. We advise that you stop the unit and follow the water drain-off procedure for this component. We recommend an early resample in 500 hours to monitor this condition.All component wear rates are normal. Appearance is hazy. Free water present. There is a light concentration of water present in the oil. There is a moderate amount of visible silt present in the sample. The condition of the oil is suitable for further service.

view report

27 Oct 2022 Diag: Don Baldridge

ISO

Oil and filter change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

view report

KAESER COMPRESSORS
Built for a lifetime.

OIL ANALYSIS REPORT

Sample Rating Trend



WATER

Machine Id
KAESER SM 7.5 8105335 (S/N 1213)
Component
Compressor
Fluid
KAESER SIGMA (OEM) S-460 (--- GAL)

DIAGNOSIS

Recommendation

We recommend you service the filters on this component. We were unable to perform a particle count due to a high concentration of particles present in this sample. We advise that you stop the unit and follow the water drain-off procedure for this component. We recommend an early resample in 500 hours to monitor this condition.

Wear

All component wear rates are normal.

Contamination

There is a light concentration of water present in the oil. High concentration of visible dirt/debris present in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**KCPA009796**	KCP53290	KCP46780D
Sample Date		Client Info		**14 Nov 2023**	28 May 2023	27 Oct 2022
Machine Age	hrs	Client Info		**4914**	3452	1914
Oil Age	hrs	Client Info		**0**	1500	1914
Oil Changed		Client Info		**N/A**	Not Changd	Changed
Sample Status				**ABNORMAL**	ABNORMAL	ABNORMAL

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>50	**<1**	<1	1
Chromium	ppm	ASTM D5185m	>10	**<1**	<1	0
Nickel	ppm	ASTM D5185m	>3	**<1**	<1	0
Titanium	ppm	ASTM D5185m	>3	**<1**	<1	0
Silver	ppm	ASTM D5185m	>2	**0**	<1	1
Aluminum	ppm	ASTM D5185m	>10	**2**	1	0
Lead	ppm	ASTM D5185m	>10	**0**	<1	0
Copper	ppm	ASTM D5185m	>50	**10**	4	7
Tin	ppm	ASTM D5185m	>10	**0**	<1	0
Vanadium	ppm	ASTM D5185m		**0**	<1	0
Cadmium	ppm	ASTM D5185m		**<1**	<1	0

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		**0**	0	0
Barium	ppm	ASTM D5185m	90	**0**	0	0
Molybdenum	ppm	ASTM D5185m		**<1**	<1	0
Manganese	ppm	ASTM D5185m		**<1**	<1	<1
Magnesium	ppm	ASTM D5185m	90	**14**	44	23
Calcium	ppm	ASTM D5185m	2	**2**	0	0
Phosphorus	ppm	ASTM D5185m		**0**	0	6
Zinc	ppm	ASTM D5185m		**21**	8	37
Sulfur	ppm	ASTM D5185m		**21318**	20155	21369

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	**<1**	2	<1
Sodium	ppm	ASTM D5185m		**5**	5	8
Potassium	ppm	ASTM D5185m	>20	**2**	<1	2
Water	%	ASTM D6304	>0.05	▲ **0.077**	▲ 0.120	0.018
ppm Water	ppm	ASTM D6304	>500	▲ **770**	▲ 1200	185.4

FLUID CLEANLINESS		method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647		**---**	---	9012
Particles >6µm		ASTM D7647	>1300	**---**	---	▲ 2811
Particles >14µm		ASTM D7647	>80	**---**	---	▲ 139
Particles >21µm		ASTM D7647	>20	**---**	---	▲ 31
Particles >38µm		ASTM D7647	>4	**---**	---	2
Particles >71µm		ASTM D7647	>3	**---**	---	0
Oil Cleanliness		ISO 4406 (c)	>--/17/13	**---**	---	▲ 20/19/14

FLUID DEGRADATION		method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	0.4	**0.28**	0.33	0.30

KAESER COMPRESSORS
Built for a lifetime.

OIL ANALYSIS REPORT







VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Precipitate	scalar	*Visual	NONE	**NONE**	NONE	NONE
Silt	scalar	*Visual	NONE	**NONE**	▲ MODER	NONE
Debris	scalar	*Visual	NONE	▲ **HEAVY**	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Appearance	scalar	*Visual	NORML	**NORML**	▲ HAZY	NORML
Odor	scalar	*Visual	NORML	**NORML**	NORML	NORML
Emulsified Water	scalar	*Visual	>0.05	**0.2%**	0.2%	NEG
Free Water	scalar	*Visual		**NEG**	▲ 2.0	NEG

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	46	**43.9**	44.0	44.0

SAMPLE IMAGES	method	limit/base	current	history1	history2
Color					
Bottom					

GRAPHS









Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : KCPA009796 **Received** : 24 Nov 2023
Lab Number : 06016397 **Diagnosed** : 28 Nov 2023
Unique Number : 10755541 **Diagnostician** : Jonathan Hester
Test Package : IND 2 (Additional Tests: KF, PrtCount)

To discuss this sample report, contact Customer Service at 1-800-237-1369.
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

QUALITY ASPIRATORS
1419 GODWIN LN
DUNCANVILLE, TX
US 75116
Contact: Service Manager
T:
F: