# PROBLEM SUMMARY

Sample Rating Trend




ISO

Machine Id
## KAESER SM 12 5732576 (S/N 1926)
Component
**Compressor**
Fluid
**KAESER SIGMA (OEM) S-460 (--- GAL)**

## COMPONENT CONDITION SUMMARY

▲ Particle Trend




## RECOMMENDATION

No corrective action is recommended at this time. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

## PROBLEMATIC TEST RESULTS

| Sample Status | | | | ABNORMAL | ATTENTION | ABNORMAL |
|---|---|---|---|---|---|---|
| Particles >6µm | | ASTM D7647 | >1300 | ▲ **7857** | ▲ 1529 | ▲ 16219 |
| Particles >14µm | | ASTM D7647 | >80 | ▲ **434** | ▲ 104 | ▲ 1441 |
| Particles >21µm | | ASTM D7647 | >20 | ▲ **87** | 21 | ▲ 390 |
| Oil Cleanliness | | ISO 4406 (c) | >--/17/13 | ▲ **22/20/16** | ▲ 18/14 | ▲ 21/18 |

**Customer Id:** AMBROC
**Sample No.:** KCPA010809
**Lab Number:** 06027174
**Test Package:** IND 2

*To manage this report scan the QR code*

*To discuss the diagnosis or test data:*
Don Baldridge +1
don.b505@comcast.net

*To change component or sample information:*
Customer Service +1 1-800-237-1369
customerservice@wearcheck.com

## RECOMMENDED ACTIONS

*There are no recommended actions for this sample.*

## HISTORICAL DIAGNOSIS

**30 Jul 2021 Diag: Angela Borella**

ISO

Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor.All component wear rates are normal. There is a moderate amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

**view report**

**05 Jul 2019 Diag: Don Baldridge**

ISO

No corrective action is recommended at this time. Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

**view report**

KAESER COMPRESSORS
Built for a lifetime.

# OIL ANALYSIS REPORT

Sample Rating Trend




ISO

Machine Id
## KAESER SM 12 5732576 (S/N 1926)
Component
**Compressor**
Fluid
**KAESER SIGMA (OEM) S-460 (--- GAL)**

## DIAGNOSIS

**▲ Recommendation**
No corrective action is recommended at this time. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

**Wear**
All component wear rates are normal.

**▲ Contamination**
There is a high amount of particulates present in the oil.

**Fluid Condition**
The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

| SAMPLE INFORMATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Sample Number | | Client Info | | **KCPA010809** | KCP41703 | KCP17096 |
| Sample Date | | Client Info | | **29 Nov 2023** | 30 Jul 2021 | 05 Jul 2019 |
| Machine Age | hrs | Client Info | | **14585** | 10108 | 22566 |
| Oil Age | hrs | Client Info | | **0** | 3000 | 8000 |
| Oil Changed | | Client Info | | **N/A** | Changed | Changed |
| Sample Status | | | | **ABNORMAL** | ATTENTION | ABNORMAL |

| WEAR METALS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Iron | ppm | ASTM D5185m | >50 | **<1** | 0 | 1 |
| Chromium | ppm | ASTM D5185m | >10 | **<1** | 0 | 0 |
| Nickel | ppm | ASTM D5185m | >3 | **0** | 0 | 0 |
| Titanium | ppm | ASTM D5185m | >3 | **0** | 0 | 0 |
| Silver | ppm | ASTM D5185m | >2 | **0** | 0 | 0 |
| Aluminum | ppm | ASTM D5185m | >10 | **2** | 0 | <1 |
| Lead | ppm | ASTM D5185m | >10 | **0** | 0 | <1 |
| Copper | ppm | ASTM D5185m | >50 | **8** | 4 | 7 |
| Tin | ppm | ASTM D5185m | >10 | **0** | 0 | <1 |
| Antimony | ppm | ASTM D5185m | | **---** | 0 | 0 |
| Vanadium | ppm | ASTM D5185m | | **0** | 0 | 0 |
| Cadmium | ppm | ASTM D5185m | | **0** | 0 | 0 |

| ADDITIVES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Boron | ppm | ASTM D5185m | | **0** | 0 | <1 |
| Barium | ppm | ASTM D5185m | 90 | **0** | 0 | <1 |
| Molybdenum | ppm | ASTM D5185m | | **0** | 0 | 0 |
| Manganese | ppm | ASTM D5185m | | **0** | 0 | <1 |
| Magnesium | ppm | ASTM D5185m | 90 | **36** | 40 | 45 |
| Calcium | ppm | ASTM D5185m | 2 | **<1** | 0 | <1 |
| Phosphorus | ppm | ASTM D5185m | | **0** | 3 | 2 |
| Zinc | ppm | ASTM D5185m | | **0** | 1 | 8 |
| Sulfur | ppm | ASTM D5185m | | **18436** | 16169 | 23737 |

| CONTAMINANTS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Silicon | ppm | ASTM D5185m | >25 | **0** | 0 | 1 |
| Sodium | ppm | ASTM D5185m | | **14** | 17 | 15 |
| Potassium | ppm | ASTM D5185m | >20 | **2** | 3 | 1 |
| Water | % | ASTM D6304 | >0.05 | **0.008** | 0.022 | 0.025 |
| ppm Water | ppm | ASTM D6304 | >500 | **85** | 226.0 | 250 |

| FLUID CLEANLINESS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Particles >4µm | | ASTM D7647 | | **25017** | 6485 | 48041 |
| Particles >6µm | | ASTM D7647 | >1300 | ▲ **7857** | ▲ 1529 | ▲ 16219 |
| Particles >14µm | | ASTM D7647 | >80 | ▲ **434** | ▲ 104 | ▲ 1441 |
| Particles >21µm | | ASTM D7647 | >20 | ▲ **87** | 21 | ▲ 390 |
| Particles >38µm | | ASTM D7647 | >4 | **2** | 0 | ▲ 16 |
| Particles >71µm | | ASTM D7647 | >3 | **0** | 0 | 0 |
| Oil Cleanliness | | ISO 4406 (c) | >--/17/13 | ▲ **22/20/16** | ▲ 18/14 | ▲ 21/18 |

| FLUID DEGRADATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Acid Number (AN) | mg KOH/g | ASTM D8045 | 0.4 | **0.27** | 0.350 | 0.323 |

KAESER COMPRESSORS
Built for a lifetime.

# OIL ANALYSIS REPORT

Particle Trend




Water (KF)




Acid Number




Water (KF)




Viscosity @ 40°C




| VISUAL | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| White Metal | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Yellow Metal | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Precipitate | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Silt | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Debris | scalar | *Visual | NONE | **NONE** | NONE | LIGHT |
| Sand/Dirt | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Appearance | scalar | *Visual | NORML | **NORML** | NORML | NORML |
| Odor | scalar | *Visual | NORML | **NORML** | NORML | NORML |
| Emulsified Water | scalar | *Visual | >0.05 | **NEG** | NEG | NEG |
| Free Water | scalar | *Visual | | **NEG** | NEG | NEG |

| FLUID PROPERTIES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Visc @ 40°C | cSt | ASTM D445 | 46 | **44.2** | 44.5 | 43.7 |

| SAMPLE IMAGES | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|
| Color | | |  | | |
| Bottom | | |  | | |

## GRAPHS

Ferrous Alloys




Non-ferrous Metals




Viscosity @ 40°C




Particle Count




Acid Number




Certificate L2367

**Laboratory** : WearCheck USA - 501 Madison Ave., Cary, NC 27513
**Sample No.** : KCPA010809 **Received** : 06 Dec 2023
**Lab Number** : 06027174 **Diagnosed** : 08 Dec 2023
**Unique Number** : 10776965 **Diagnostician** : Don Baldridge
**Test Package** : IND 2 ( Additional Tests: KF, PrtCount )

*To discuss this sample report, contact Customer Service at 1-800-237-1369.*
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
*Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)*

**AMBASSADOR PACKAGING**
2268 OLD YORK RD
ROCK HILL, SC
US 29731
Contact: Service Manager
T:
F: