# OIL ANALYSIS REPORT

Sample Rating Trend




NORMAL

Machine Id
## CT-8 - B2 TUMBLER
Component
**Pump**
Fluid
**USPI VAC 100 (--- LTR)**

## DIAGNOSIS

**Recommendation**
Resample at the next service interval to monitor.

**Wear**
All component wear rates are normal.

**Contamination**
There is no indication of any contamination in the oil. The amount and size of particulates present in the system are acceptable.

**Fluid Condition**
The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

| SAMPLE INFORMATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Sample Number | | Client Info | | **USPM31953** | USPM29391 | USPM28407 |
| Sample Date | | Client Info | | **30 Nov 2023** | 18 Aug 2023 | 23 May 2023 |
| Machine Age | hrs | Client Info | | **0** | 0 | 0 |
| Oil Age | hrs | Client Info | | **0** | 0 | 0 |
| Oil Changed | | Client Info | | **N/A** | N/A | N/A |
| Sample Status | | | | **NORMAL** | NORMAL | ABNORMAL |

| WEAR METALS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Iron | ppm | ASTM D5185m | >90 | **0** | <1 | <1 |
| Chromium | ppm | ASTM D5185m | >5 | **<1** | 0 | <1 |
| Nickel | ppm | ASTM D5185m | >5 | **0** | 0 | <1 |
| Titanium | ppm | ASTM D5185m | >3 | **<1** | 0 | 0 |
| Silver | ppm | ASTM D5185m | >3 | **0** | 0 | 0 |
| Aluminum | ppm | ASTM D5185m | >7 | **0** | 0 | 0 |
| Lead | ppm | ASTM D5185m | >12 | **0** | 0 | 1 |
| Copper | ppm | ASTM D5185m | >30 | **0** | 0 | 0 |
| Tin | ppm | ASTM D5185m | >9 | **0** | 0 | <1 |
| Vanadium | ppm | ASTM D5185m | | **0** | 0 | 0 |
| Cadmium | ppm | ASTM D5185m | | **0** | 0 | 0 |

| ADDITIVES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Boron | ppm | ASTM D5185m | 0 | **0** | 0 | 0 |
| Barium | ppm | ASTM D5185m | 0 | **0** | 0 | 0 |
| Molybdenum | ppm | ASTM D5185m | 0 | **0** | 0 | 0 |
| Manganese | ppm | ASTM D5185m | | **0** | 0 | <1 |
| Magnesium | ppm | ASTM D5185m | 0 | **<1** | 0 | 0 |
| Calcium | ppm | ASTM D5185m | 0 | **0** | 2 | 0 |
| Phosphorus | ppm | ASTM D5185m | 1800 | **1490** | 1134 | 1343 |
| Zinc | ppm | ASTM D5185m | 0 | **0** | 0 | 0 |
| Sulfur | ppm | ASTM D5185m | 0 | **0** | 18 | 0 |

| CONTAMINANTS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Silicon | ppm | ASTM D5185m | >60 | **9** | 6 | 6 |
| Sodium | ppm | ASTM D5185m | | **2** | 0 | 0 |
| Potassium | ppm | ASTM D5185m | >20 | **<1** | 0 | 2 |
| Water | % | ASTM D6304 | >.1 | **0.041** | 0.075 | 0.050 |
| ppm Water | ppm | ASTM D6304 | >1000 | **413** | 753.3 | 506.5 |

| FLUID CLEANLINESS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Particles >4µm | | ASTM D7647 | >10000 | **823** | 642 | 8458 |
| Particles >6µm | | ASTM D7647 | >2500 | **206** | 300 | ▲ 6951 |
| Particles >14µm | | ASTM D7647 | >640 | **51** | 46 | ▲ 1516 |
| Particles >21µm | | ASTM D7647 | >160 | **3** | 9 | 134 |
| Particles >38µm | | ASTM D7647 | >40 | **1** | 0 | 1 |
| Particles >71µm | | ASTM D7647 | >10 | **0** | 0 | 0 |
| Oil Cleanliness | | ISO 4406 (c) | >20/18/16 | **17/17/16** | 17/15/13 | ▲ 20/20/18 |

| FLUID DEGRADATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Acid Number (AN) | mg KOH/g | ASTM D8045 | 0.05 | **0.20** | 0.17 | 0.27 |

# OIL ANALYSIS REPORT

Water (KF)




Particle Trend




Water (KF)




Viscosity @ 40°C




Particle Trend




| VISUAL | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| White Metal | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Yellow Metal | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Precipitate | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Silt | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Debris | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Sand/Dirt | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Appearance | scalar | *Visual | NORML | **NORML** | NORML | NORML |
| Odor | scalar | *Visual | NORML | **NORML** | NORML | NORML |
| Emulsified Water | scalar | *Visual | >.1 | **NEG** | NEG | NEG |
| Free Water | scalar | *Visual | | **NEG** | NEG | NEG |

| FLUID PROPERTIES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Visc @ 40°C | cSt | ASTM D445 | 91 | **96.8** | 95.6 | 95.5 |

| SAMPLE IMAGES | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|
| Color | | |  | | |
| Bottom | | |  | | |

## GRAPHS

Ferrous Alloys




Particle Count




Non-ferrous Metals




Viscosity @ 40°C




Acid Number




Certificate L2367

**Laboratory** : WearCheck USA - 501 Madison Ave., Cary, NC 27513
**Sample No.** : USPM31953
**Lab Number** : 06027791
**Unique Number** : 10777582
**Test Package** : IND 2

**Received** : 07 Dec 2023
**Diagnosed** : 08 Dec 2023
**Diagnostician** : Doug Bogart

*To discuss this sample report, contact Customer Service at 1-800-237-1369.*
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
*Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)*

**KraftHeinz - Davenport - Plant 8394**
9401 GRANITE DRIVE
DAVENPORT, IA
US 52802
Contact: JOHN KONRAD
john.konrad@kraftheinz.com
T:
F: (563)326-8391