# PROBLEM SUMMARY

Sample Rating Trend




ISO

Machine Id
## WHITNEY ASSEMBLY 1634
Component
**Hydraulic System**
Fluid
**DUBOIS PRELUBE ISO 46 (140 GAL)**

## COMPONENT CONDITION SUMMARY




## RECOMMENDATION

We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. We recommend an early resample to monitor this condition.

## PROBLEMATIC TEST RESULTS

| Sample Status | | | | ABNORMAL | ABNORMAL | NORMAL |
|---|---|---|---|---|---|---|
| Particles >4µm | | ASTM D7647 | >2500 | ▲ **6565** | ▲ 6178 | 546 |
| Particles >6µm | | ASTM D7647 | >640 | ▲ **2428** | ▲ 787 | 110 |
| Particles >14µm | | ASTM D7647 | >80 | ▲ **336** | 35 | 9 |
| Particles >21µm | | ASTM D7647 | >20 | ▲ **100** | 9 | 3 |
| Oil Cleanliness | | ISO 4406 (c) | >18/16/13 | ▲ **20/18/16** | ▲ 20/17/12 | 16/14/10 |

**Customer Id:** LARATT
**Sample No.:** ST44428
**Lab Number:** 06029377
**Test Package:** IND 2

*To manage this report scan the QR code*

*To discuss the diagnosis or test data:*
Wes Davis +1 905-569-8600 x223
wesd@wearcheck.ca

*To change component or sample information:*
Customer Service +1 1-800-237-1369
customerservice@wearcheck.com

## RECOMMENDED ACTIONS

| Action | Status | Date | Done By | Description |
|---|---|---|---|---|
| Change Filter | --- | --- | ? | We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. |
| Resample | --- | --- | ? | We recommend an early resample to monitor this condition. |
| Filter Fluid | --- | --- | ? | We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. |

## HISTORICAL DIAGNOSIS

**07 Dec 2022 Diag: Doug Bogart**

ISO

We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor. Due to an abnormal test result it is recommended to contact Stauff Corp at (201)-444-7800 for help resolving the issue.All component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

view report

---

**24 Nov 2021 Diag: Don Baldridge**

NORMAL

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The amount and size of particulates present in the system are acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

view report

---

**09 Dec 2020 Diag: Angela Borella**

NORMAL

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The amount and size of particulates present in the system are acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

view report

STAUFF FILTRATION TECHNOLOGY

# OIL ANALYSIS REPORT

Sample Rating Trend




ISO

Machine Id
## WHITNEY ASSEMBLY 1634
Component
**Hydraulic System**
Fluid
**DUBOIS PRELUBE ISO 46 (140 GAL)**

## DIAGNOSIS

**Recommendation**
We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. We recommend an early resample to monitor this condition.

**Wear**
All component wear rates are normal.

**Contamination**
There is a moderate amount of particulates (2 to 100 microns in size) present in the oil. The system cleanliness is above the acceptable limit for the target ISO 4406 cleanliness code.

**Fluid Condition**
The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

| SAMPLE INFORMATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Sample Number | | Client Info | | **ST44428** | ST44990 | ST39923 |
| Sample Date | | Client Info | | **29 Nov 2023** | 07 Dec 2022 | 24 Nov 2021 |
| Machine Age | hrs | Client Info | | **0** | 0 | 0 |
| Oil Age | hrs | Client Info | | **0** | 0 | 0 |
| Oil Changed | | Client Info | | **N/A** | N/A | N/A |
| Sample Status | | | | **ABNORMAL** | ABNORMAL | NORMAL |

| WEAR METALS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Iron | ppm | ASTM D5185m | >20 | **15** | 12 | 8 |
| Chromium | ppm | ASTM D5185m | >20 | **1** | <1 | <1 |
| Nickel | ppm | ASTM D5185m | >20 | **<1** | <1 | 0 |
| Titanium | ppm | ASTM D5185m | | **<1** | 0 | 0 |
| Silver | ppm | ASTM D5185m | | **0** | 0 | <1 |
| Aluminum | ppm | ASTM D5185m | >20 | **2** | <1 | 0 |
| Lead | ppm | ASTM D5185m | >20 | **0** | <1 | 0 |
| Copper | ppm | ASTM D5185m | >20 | **6** | 5 | 4 |
| Tin | ppm | ASTM D5185m | >20 | **<1** | <1 | <1 |
| Antimony | ppm | ASTM D5185m | | **---** | --- | 0 |
| Vanadium | ppm | ASTM D5185m | | **0** | 0 | 0 |
| Cadmium | ppm | ASTM D5185m | | **<1** | 0 | 0 |

| ADDITIVES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Boron | ppm | ASTM D5185m | | **0** | 0 | 2 |
| Barium | ppm | ASTM D5185m | | **0** | 0 | 0 |
| Molybdenum | ppm | ASTM D5185m | | **<1** | 0 | 0 |
| Manganese | ppm | ASTM D5185m | | **<1** | <1 | 0 |
| Magnesium | ppm | ASTM D5185m | | **<1** | <1 | 0 |
| Calcium | ppm | ASTM D5185m | | **70** | 60 | 96 |
| Phosphorus | ppm | ASTM D5185m | | **729** | 695 | 699 |
| Zinc | ppm | ASTM D5185m | | **912** | 817 | 804 |
| Sulfur | ppm | ASTM D5185m | | **2303** | 2411 | 1854 |

| CONTAMINANTS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Silicon | ppm | ASTM D5185m | >15 | **2** | 1 | 0 |
| Sodium | ppm | ASTM D5185m | | **3** | 2 | 3 |
| Potassium | ppm | ASTM D5185m | >20 | **1** | <1 | 1 |
| Water | % | ASTM D6304 | >0.05 | **0.003** | 0.010 | 0.007 |
| ppm Water | ppm | ASTM D6304 | >500 | **33** | 103.4 | 78.1 |

| FLUID CLEANLINESS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Particles >4µm | | ASTM D7647 | >2500 | ▲ **6565** | ▲ 6178 | 546 |
| Particles >6µm | | ASTM D7647 | >640 | ▲ **2428** | ▲ 787 | 110 |
| Particles >14µm | | ASTM D7647 | >80 | ▲ **336** | 35 | 9 |
| Particles >21µm | | ASTM D7647 | >20 | ▲ **100** | 9 | 3 |
| Particles >38µm | | ASTM D7647 | >4 | **5** | 1 | 0 |
| Particles >71µm | | ASTM D7647 | >3 | **0** | 0 | 0 |
| Oil Cleanliness | | ISO 4406 (c) | >18/16/13 | ▲ **20/18/16** | ▲ 20/17/12 | 16/14/10 |

| FLUID DEGRADATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Acid Number (AN) | mg KOH/g | ASTM D8045 | | **0.30** | 0.33 | 0.099 |

# OIL ANALYSIS REPORT

STAUFF FILTRATION TECHNOLOGY

Particle Trend




Water (KF)




Acid Number




Water (KF)




Viscosity @ 40°C




| VISUAL | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| White Metal | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Yellow Metal | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Precipitate | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Silt | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Debris | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Sand/Dirt | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Appearance | scalar | *Visual | NORML | **NORML** | NORML | NORML |
| Odor | scalar | *Visual | NORML | **NORML** | NORML | NORML |
| Emulsified Water | scalar | *Visual | >0.05 | **NEG** | NEG | NEG |
| Free Water | scalar | *Visual | | **NEG** | NEG | NEG |

| FLUID PROPERTIES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Visc @ 40°C | cSt | ASTM D445 | | **46.2** | 46.4 | 46.5 |

| SAMPLE IMAGES | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|
| Color | | |  | | |
| Bottom | | |  | | |

## GRAPHS

Ferrous Alloys




Non-ferrous Metals




Viscosity @ 40°C




Particle Count




Acid Number




Certificate L2367

**Laboratory** : WearCheck USA - 501 Madison Ave., Cary, NC 27513
**Sample No.** : ST44428 **Received** : 08 Dec 2023
**Lab Number** : 06029377 **Diagnosed** : 11 Dec 2023
**Unique Number** : 10779168 **Diagnostician** : Wes Davis
**Test Package** : IND 2 ( Additional Tests: KF )

*To discuss this sample report, contact Customer Service at 1-800-237-1369.*
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
*Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)*

**LARSON TOOL & STAMPING CO**
90 OLIVE ST
ATTLEBORO, MA
US 02703
Contact: DAVE SIMCOCK
dsimcock@larsontool.com
T: (508)222-0897
F: