PROBLEM SUMMARY

Sample Rating Trend

ISO

Machine Id
DAEWOO PUMA 12L
Component
Hydraulic System
Fluid
MOBIL DTE ULTRA 24 ISO 32 (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

We recommend you service the filters on this component. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS

Sample Status				**ABNORMAL**	---	---
Particles >4µm		ASTM D7647	>10000	▲ **86284**	---	---
Particles >6µm		ASTM D7647	>2500	▲ **28565**	---	---
Particles >14µm		ASTM D7647	>320	▲ **1010**	---	---
Particles >21µm		ASTM D7647	>80	▲ **176**	---	---
Oil Cleanliness		ISO 4406 (c)	>20/18/15	▲ **24/22/17**	---	---
PrtFilter					*no image*	*no image*

Customer Id: LINORA
Sample No.: PH0003688
Lab Number: 06029982
Test Package: PLANT

To manage this report scan the QR code

To discuss the diagnosis or test data:
Jonathan Hester +1 919-379-4092 x4092
jhester@wearcheckusa.com

To change component or sample information:
Customer Service +1 1-800-237-1369
customerservice@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Filter	---	---	?	We recommend you service the filters on this component.

HISTORICAL DIAGNOSIS

OIL ANALYSIS REPORT

Sample Rating Trend

ISO

Machine Id
DAEWOO PUMA 12L
Component
Hydraulic System
Fluid
MOBIL DTE ULTRA 24 ISO 32 (--- GAL)

DIAGNOSIS

Recommendation
We recommend you service the filters on this component. Resample at the next service interval to monitor.

Wear
All component wear rates are normal.

Contamination
There is a high amount of particulates present in the oil.

Fluid Condition
The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

Particle Filter (Magn: 200 x)



SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**PH0003688**	---	---
Sample Date		Client Info		**06 Dec 2023**	---	---
Machine Age	yrs	Client Info		**0**	---	---
Oil Age	yrs	Client Info		**1**	---	---
Oil Changed		Client Info		**N/A**	---	---
Sample Status				**ABNORMAL**	---	---

CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method	>0.05	**NEG**	---	---

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	**4**	---	---
Chromium	ppm	ASTM D5185m	>20	**0**	---	---
Nickel	ppm	ASTM D5185m	>20	**0**	---	---
Titanium	ppm	ASTM D5185m		**<1**	---	---
Silver	ppm	ASTM D5185m		**0**	---	---
Aluminum	ppm	ASTM D5185m	>20	**0**	---	---
Lead	ppm	ASTM D5185m	>20	**0**	---	---
Copper	ppm	ASTM D5185m	>20	**<1**	---	---
Tin	ppm	ASTM D5185m	>20	**0**	---	---
Vanadium	ppm	ASTM D5185m		**0**	---	---
Cadmium	ppm	ASTM D5185m		**0**	---	---

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		**0**	---	---
Barium	ppm	ASTM D5185m		**0**	---	---
Molybdenum	ppm	ASTM D5185m		**0**	---	---
Manganese	ppm	ASTM D5185m		**0**	---	---
Magnesium	ppm	ASTM D5185m		**0**	---	---
Calcium	ppm	ASTM D5185m		**82**	---	---
Phosphorus	ppm	ASTM D5185m		**415**	---	---
Zinc	ppm	ASTM D5185m		**617**	---	---
Sulfur	ppm	ASTM D5185m		**4486**	---	---

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	**<1**	---	---
Sodium	ppm	ASTM D5185m		**2**	---	---
Potassium	ppm	ASTM D5185m	>20	**<1**	---	---

FLUID CLEANLINESS		method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>10000	▲ **86284**	---	---
Particles >6µm		ASTM D7647	>2500	▲ **28565**	---	---
Particles >14µm		ASTM D7647	>320	▲ **1010**	---	---
Particles >21µm		ASTM D7647	>80	▲ **176**	---	---
Particles >38µm		ASTM D7647	>20	**5**	---	---
Particles >71µm		ASTM D7647	>4	**1**	---	---
Oil Cleanliness		ISO 4406 (c)	>20/18/15	▲ **24/22/17**	---	---

FLUID DEGRADATION		method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		**0.57**	---	---

OIL ANALYSIS REPORT

Particle Count



Particle Trend



Acid Number

Viscosity @ 40°C



VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	**NONE**	---	---
Yellow Metal	scalar	*Visual	NONE	**NONE**	---	---
Precipitate	scalar	*Visual	NONE	**NONE**	---	---
Silt	scalar	*Visual	NONE	**NONE**	---	---
Debris	scalar	*Visual	NONE	**NONE**	---	---
Sand/Dirt	scalar	*Visual	NONE	**NONE**	---	---
Appearance	scalar	*Visual	NORML	**NORML**	---	---
Odor	scalar	*Visual	NORML	**NORML**	---	---
Emulsified Water	scalar	*Visual	>0.05	**NEG**	---	---
Free Water	scalar	*Visual		**NEG**	---	---

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	33.4	**33.3**	---	---

SAMPLE IMAGES	method	limit/base	current	history1	history2
Color				*no image*	*no image*
Bottom				*no image*	*no image*
PrtFilter				*no image*	*no image*

GRAPHS

Ferrous Alloys

Non-ferrous Metals

Viscosity @ 40°C



Particle Filter (Magn: 200 x)



Acid Number



Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : PH0003688 **Received** : 08 Dec 2023
Lab Number : 06029982 **Diagnosed** : 13 Dec 2023
Unique Number : 10779773 **Diagnostician** : Jonathan Hester
Test Package : PLANT (Additional Tests: PrtFilter)

To discuss this sample report, contact Customer Service at 1-800-237-1369.
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

LINDE ADVANCED MATERIALS TECHNOLOGIES
542 ROUTE 303
ORANGEBURG, NY
US 10920
Contact: THOMAS BIGGIE
thomas.biggie@linde.com
T:
F: