OIL ANALYSIS REPORT

Area
OKLAHOMA/102/EG - ROLLER/COMPACTOR
Machine Id
64.21L [OKLAHOMA^102^EG - ROLLER/COMPACTOR]
Component
Right Gear Drive
Fluid
MOBIL SHC 630 (--- GAL)

Sample Rating Trend



NORMAL

DIAGNOSIS

Recommendation
Resample at the next service interval to monitor.

Wear
All component wear rates are normal.

Contamination
There is no indication of any contamination in the oil.

Fluid Condition
The condition of the oil is acceptable for the time in service.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**WC0873909**	WCMCF30743	WC57567068
Sample Date		Client Info		**12 Mar 2024**	06 Mar 2017	30 May 2012
Machine Age	hrs	Client Info		**2703**	3096	1074
Oil Age	hrs	Client Info		**1000**	250	---
Oil Changed		Client Info		**Not Changd**	Changed	N/A
Sample Status				**NORMAL**	ABNORMAL	NORMAL

CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method	>0.2	**NEG**	NEG	NEG

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>500	**10**	8	3
Chromium	ppm	ASTM D5185m	>5	**<1**	<1	0
Nickel	ppm	ASTM D5185m	>8	**<1**	0	0
Titanium	ppm	ASTM D5185m		**<1**	0	0
Silver	ppm	ASTM D5185m		**0**	0	0
Aluminum	ppm	ASTM D5185m	>20	**2**	0	0
Lead	ppm	ASTM D5185m	>20	**<1**	0	0
Copper	ppm	ASTM D5185m	>500	**22**	19	5
Tin	ppm	ASTM D5185m	>75	**<1**	2	0
Antimony	ppm	ASTM D5185m	>5	**---**	0	---
Vanadium	ppm	ASTM D5185m		**<1**	0	0
Cadmium	ppm	ASTM D5185m		**0**	0	0

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		**6**	<1	0
Barium	ppm	ASTM D5185m		**0**	0	0
Molybdenum	ppm	ASTM D5185m		**<1**	0	0
Manganese	ppm	ASTM D5185m		**<1**	<1	---
Magnesium	ppm	ASTM D5185m		**8**	3	2
Calcium	ppm	ASTM D5185m		**28**	29	23
Phosphorus	ppm	ASTM D5185m		**474**	485	439
Zinc	ppm	ASTM D5185m		**24**	43	33
Sulfur	ppm	ASTM D5185m		**1915**	157	---

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>35	**28**	▲ 38	13
Sodium	ppm	ASTM D5185m		**1**	2	1
Potassium	ppm	ASTM D5185m	>20	**<1**	0	0

VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	**NONE**	NONE	---
Yellow Metal	scalar	*Visual	NONE	**NONE**	NONE	---
Precipitate	scalar	*Visual	NONE	**NONE**	NONE	---
Silt	scalar	*Visual	NONE	**NONE**	NONE	---
Debris	scalar	*Visual	NONE	**NONE**	NONE	---
Sand/Dirt	scalar	*Visual	NONE	**NONE**	NONE	---
Appearance	scalar	*Visual	NORML	**NORML**	NORML	---
Odor	scalar	*Visual	NORML	**NORML**	NORML	---
Emulsified Water	scalar	*Visual	>0.2	**NEG**	NEG	---
Free Water	scalar	*Visual		**NEG**	NEG	---

OIL ANALYSIS REPORT



FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	217.7	**214**	214.9	216.5

SAMPLE IMAGES	method	limit/base	current	history1	history2
Color			*no image*	*no image*	*no image*
Bottom			*no image*	*no image*	*no image*

GRAPHS







Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : WC0873909
Lab Number : 06132396
Unique Number : 10951861
Test Package : CONST

Received : 28 Mar 2024
Tested : 04 Apr 2024
Diagnosed : 04 Apr 2024 - Wes Davis

To discuss this sample report, contact Customer Service at 1-800-237-1369.
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

SHERWOOD CONSTRUCTION CO INC
3219 WEST MAY ST
WICHITA, KS
US 67213
Contact: DOUG KING
doug.king@sherwood.net
T: (316)617-3161
F: x:

Report Id: SHEWIC [WUSCAR] 06132396 (Generated: 04/05/2024 04:04:18) Rev: 1

Submitted By: RUSTY RILEY