OIL ANALYSIS REPORT

Sample Rating Trend



NORMAL

Machine Id
GENERAC RAND. CO. EMS 5
Component
Propane Engine
Fluid
SHELL ROTELLA T 15W40 (6 QTS)

DIAGNOSIS

Recommendation
Resample at the next service interval to monitor.

Wear
Metal levels are typical for a new component breaking in.

Contamination
There is no indication of any contamination in the oil.

Fluid Condition
The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**WC0887900**	WC0682865	WCM1369841
Sample Date		Client Info		**21 Feb 2024**	16 Jan 2023	23 Jan 2017
Machine Age	hrs	Client Info		**139**	22	46
Oil Age	hrs	Client Info		**0**	0	0
Oil Changed		Client Info		**Changed**	N/A	Changed
Sample Status				**NORMAL**	NORMAL	NORMAL

CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method	>0.1	**NEG**	NEG	NEG

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>100	**4**	6	3
Chromium	ppm	ASTM D5185m	>25	**<1**	0	0
Nickel	ppm	ASTM D5185m	>5	**1**	0	0
Titanium	ppm	ASTM D5185m		**<1**	0	<1
Silver	ppm	ASTM D5185m	>5	**0**	2	0
Aluminum	ppm	ASTM D5185m	>20	**4**	<1	1
Lead	ppm	ASTM D5185m	>25	**1**	0	0
Copper	ppm	ASTM D5185m	>35	**1**	<1	1
Tin	ppm	ASTM D5185m	>8	**1**	0	0
Antimony	ppm	ASTM D5185m		**---**	---	2
Vanadium	ppm	ASTM D5185m		**<1**	0	0
Cadmium	ppm	ASTM D5185m		**2**	0	0

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	316	**157**	57	10
Barium	ppm	ASTM D5185m	0.0	**<1**	0	0
Molybdenum	ppm	ASTM D5185m	1.2	**116**	76	51
Manganese	ppm	ASTM D5185m		**1**	<1	<1
Magnesium	ppm	ASTM D5185m	24	**165**	202	869
Calcium	ppm	ASTM D5185m	2292	**2717**	1821	1132
Phosphorus	ppm	ASTM D5185m	1064	**1408**	823	979
Zinc	ppm	ASTM D5185m	1160	**1447**	1110	1108
Sulfur	ppm	ASTM D5185m	4996	**5380**	3473	2869

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	**6**	8	6
Sodium	ppm	ASTM D5185m		**5**	2	4
Potassium	ppm	ASTM D5185m	>20	**2**	2	1

INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844		**0**	0.1	0
Nitration	Abs/cm	*ASTM D7624	>20	**6.6**	6.7	4.
Sulfation	Abs/.1mm	*ASTM D7415	>30	**16.1**	16.6	13.

FLUID DEGRADATION		method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	**12.0**	11.5	10.
Base Number (BN)	mg KOH/g	ASTM D2896	10.1	**6.8**	7.9	---

OIL ANALYSIS REPORT

FT-IR (Direct Trend)



Base Number



Viscosity @ 100°C



VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Precipitate	scalar	*Visual	NONE	**NONE**	NONE	NONE
Silt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Debris	scalar	*Visual	NONE	**NONE**	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Appearance	scalar	*Visual	NORML	**NORML**	NORML	NORML
Odor	scalar	*Visual	NORML	**NORML**	NORML	NORML
Emulsified Water	scalar	*Visual	>0.1	**NEG**	NEG	NEG
Free Water	scalar	*Visual		**NEG**	NEG	NEG

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D445	15.7	**13.8**	13.8	15.6

GRAPHS

Iron (ppm)



Lead (ppm)



Aluminum (ppm)



Chromium (ppm)



Copper (ppm)



Silicon (ppm)



Viscosity @ 100°C



Base Number



Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : WC0887900 **Received** : 12 Apr 2024
Lab Number : 06146941 **Tested** : 15 Apr 2024
Unique Number : 10977019 **Diagnosed** : 15 Apr 2024 - Sean Felton
Test Package : MOB 1

To discuss this sample report, contact Customer Service at 1-800-237-1369.
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

PIEDMONT GENERATOR
7560 NC HWY 22 NORTH
CLIMAX, NC
US 27233
Contact: TERRY SHEPPARD
terry1pg@bellsouth.net; bill3pg@bellsouth.net
T: (336)685-4859
F: (336)685-5297