KIMBRO FLUID SOLUTIONS

# OIL ANALYSIS REPORT

Sample Rating Trend




ISO

Area
**ZANI**
Machine Id
**MITSUBISHI 210T 17**
Component
**Hydraulic System**
Fluid
**AW HYDRAULIC OIL ISO 46 (--- GAL)**

## DIAGNOSIS

**Recommendation**
We recommend you service the filters on this component. We recommend an early resample to monitor this condition. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample. Please specify the brand, type, and viscosity of the oil on your next sample.

**Wear**
All component wear rates are normal.

**Contamination**
There is a moderate amount of silt (particulates < 14 microns in size) present in the oil.

**Fluid Condition**
The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

| SAMPLE INFORMATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Sample Number | | Client Info | | **KFS0004180** | KFS0002176 | KFS0000449 |
| Sample Date | | Client Info | | **12 Apr 2024** | 18 Aug 2022 | 02 Jun 2021 |
| Machine Age | hrs | Client Info | | **0** | 0 | 0 |
| Oil Age | hrs | Client Info | | **0** | 0 | 0 |
| Oil Changed | | Client Info | | **N/A** | N/A | N/A |
| Sample Status | | | | **ABNORMAL** | ABNORMAL | ABNORMAL |

| CONTAMINATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Water | | WC Method | >0.1 | **NEG** | NEG | NEG |

| WEAR METALS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Iron | ppm | ASTM D5185m | >20 | **3** | 3 | 3 |
| Chromium | ppm | ASTM D5185m | >10 | **<1** | 0 | 0 |
| Nickel | ppm | ASTM D5185m | >10 | **<1** | <1 | 0 |
| Titanium | ppm | ASTM D5185m | | **<1** | 0 | 0 |
| Silver | ppm | ASTM D5185m | | **<1** | 0 | <1 |
| Aluminum | ppm | ASTM D5185m | >10 | **3** | <1 | 0 |
| Lead | ppm | ASTM D5185m | >10 | **<1** | 0 | <1 |
| Copper | ppm | ASTM D5185m | >75 | **4** | 2 | 1 |
| Tin | ppm | ASTM D5185m | >10 | **<1** | 0 | <1 |
| Antimony | ppm | ASTM D5185m | | **---** | --- | 0 |
| Vanadium | ppm | ASTM D5185m | | **<1** | 0 | 0 |
| Cadmium | ppm | ASTM D5185m | | **<1** | 0 | 0 |

| ADDITIVES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Boron | ppm | ASTM D5185m | 5 | **0** | <1 | 3 |
| Barium | ppm | ASTM D5185m | 5 | **0** | 0 | 0 |
| Molybdenum | ppm | ASTM D5185m | 5 | **<1** | <1 | <1 |
| Manganese | ppm | ASTM D5185m | | **<1** | 0 | 0 |
| Magnesium | ppm | ASTM D5185m | 25 | **2** | 2 | 2 |
| Calcium | ppm | ASTM D5185m | 200 | **45** | 54 | 56 |
| Phosphorus | ppm | ASTM D5185m | 300 | **331** | 332 | 315 |
| Zinc | ppm | ASTM D5185m | 370 | **414** | 454 | 420 |
| Sulfur | ppm | ASTM D5185m | 2500 | **987** | 1083 | 1030 |

| CONTAMINANTS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Silicon | ppm | ASTM D5185m | >20 | **<1** | <1 | 0 |
| Sodium | ppm | ASTM D5185m | | **0** | 0 | <1 |
| Potassium | ppm | ASTM D5185m | >20 | **2** | <1 | 0 |

| FLUID CLEANLINESS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Particles >4µm | | ASTM D7647 | >5000 | ▲ **17269** | ▲ 10833 | ▲ 21459 |
| Particles >6µm | | ASTM D7647 | >1300 | **127** | 497 | 637 |
| Particles >14µm | | ASTM D7647 | >160 | **10** | 78 | 41 |
| Particles >21µm | | ASTM D7647 | >40 | **3** | 33 | 9 |
| Particles >38µm | | ASTM D7647 | >10 | **0** | 4 | 0 |
| Particles >71µm | | ASTM D7647 | >3 | **0** | 0 | 0 |
| Oil Cleanliness | | ISO 4406 (c) | >19/17/14 | ▲ **21/14/10** | ▲ 21/16/13 | ▲ 22/16/13 |

# OIL ANALYSIS REPORT













| FLUID DEGRADATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Acid Number (AN) | mg KOH/g | ASTM D8045 | 0.57 | **0.25** | 0.28 | 0.312 |

| VISUAL | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| White Metal | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Yellow Metal | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Precipitate | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Silt | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Debris | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Sand/Dirt | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Appearance | scalar | *Visual | NORML | **NORML** | NORML | NORML |
| Odor | scalar | *Visual | NORML | **NORML** | NORML | NORML |
| Emulsified Water | scalar | *Visual | >0.1 | **NEG** | NEG | NEG |
| Free Water | scalar | *Visual | | **NEG** | NEG | NEG |

| FLUID PROPERTIES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Visc @ 40°C | cSt | ASTM D445 | 46 | **46.1** | 46.1 | 45.0 |

| SAMPLE IMAGES | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|
| Color | | | | | |
| Bottom | | | | | |



## GRAPHS
















**Laboratory** : WearCheck USA - 501 Madison Ave., Cary, NC 27513
**Sample No.** : KFS0004180
**Lab Number** : 06156884
**Unique Number** : 10992307
**Test Package** : IND 2

**Received** : 22 Apr 2024
**Tested** : 23 Apr 2024
**Diagnosed** : 23 Apr 2024 - Wes Davis

Certificate L2367

*To discuss this sample report, contact Customer Service at 1-800-237-1369.*
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
*Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)*

**ZANINI**
840 INDUSTRIAL DR
WINCHESTER, TN
US 37398
Contact: TIM DOTY
tdoty@tn.zanini.com
T:
F:

Report Id: ZANWIN [WUSCAR] 06156884 (Generated: 04/23/2024 17:33:39) Rev: 1

Submitted By: Jay Segadi