OIL ANALYSIS REPORT

Sample Rating Trend



NORMAL

Area
KANSAS
Machine Id
2000 GMC 1000-MD912
Component
Diesel Engine
Fluid
SHELL Rotella T5 15W-40 (--- QTS)

DIAGNOSIS

Recommendation
Resample at the next service interval to monitor.

Wear
All component wear rates are normal.

Contamination
There is no indication of any contamination in the oil.

Fluid Condition
The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**WC0559211**	WC0559209	WC0857194
Sample Date		Client Info		**05 Apr 2024**	07 Mar 2024	05 Jan 2024
Machine Age	mls	Client Info		**317325**	317323	317277
Oil Age	mls	Client Info		**0**	0	0
Oil Changed		Client Info		**N/A**	N/A	N/A
Sample Status				**NORMAL**	NORMAL	NORMAL

CONTAMINATION		method	limit/base	current	history1	history2
Fuel		WC Method	>5	**<1.0**	<1.0	<1.0
Water		WC Method	>0.2	**NEG**	NEG	NEG
Glycol		WC Method		**NEG**	NEG	NEG

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>100	**23**	25	20
Chromium	ppm	ASTM D5185m	>20	**<1**	<1	<1
Nickel	ppm	ASTM D5185m	>4	**0**	0	0
Titanium	ppm	ASTM D5185m		**0**	0	0
Silver	ppm	ASTM D5185m	>3	**0**	0	0
Aluminum	ppm	ASTM D5185m	>20	**2**	3	2
Lead	ppm	ASTM D5185m	>40	**1**	0	0
Copper	ppm	ASTM D5185m	>330	**1**	2	<1
Tin	ppm	ASTM D5185m	>15	**0**	<1	<1
Vanadium	ppm	ASTM D5185m		**<1**	0	0
Cadmium	ppm	ASTM D5185m		**0**	0	0

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		**184**	164	187
Barium	ppm	ASTM D5185m		**0**	0	0
Molybdenum	ppm	ASTM D5185m		**72**	73	77
Manganese	ppm	ASTM D5185m		**<1**	<1	<1
Magnesium	ppm	ASTM D5185m		**289**	294	322
Calcium	ppm	ASTM D5185m		**1986**	1918	1962
Phosphorus	ppm	ASTM D5185m		**1109**	1094	1180
Zinc	ppm	ASTM D5185m		**1269**	1256	1347
Sulfur	ppm	ASTM D5185m		**4328**	4023	4394

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	**5**	5	5
Sodium	ppm	ASTM D5185m		**2**	1	2
Potassium	ppm	ASTM D5185m	>20	**0**	<1	0

INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	**0.4**	0.4	0.4
Nitration	Abs/cm	*ASTM D7624	>20	**6.3**	6.4	6.4
Sulfation	Abs/.1mm	*ASTM D7415	>30	**18.8**	19.1	19.0

FLUID DEGRADATION		method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	**14.8**	15.2	15.2
Base Number (BN)	mg KOH/g	ASTM D2896	10	**7.9**	7.9	7.9

OIL ANALYSIS REPORT

FT-IR (Direct Trend)



Base Number



Viscosity @ 100°C



VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Precipitate	scalar	*Visual	NONE	**NONE**	NONE	NONE
Silt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Debris	scalar	*Visual	NONE	**NONE**	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Appearance	scalar	*Visual	NORML	**NORML**	NORML	NORML
Odor	scalar	*Visual	NORML	**NORML**	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	**NEG**	NEG	NEG
Free Water	scalar	*Visual		**NEG**	NEG	NEG

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D445	14.9	**11.8**	11.9	11.9

GRAPHS

Iron (ppm)



Lead (ppm)



Aluminum (ppm)



Chromium (ppm)



Copper (ppm)



Silicon (ppm)



Viscosity @ 100°C



Base Number



Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : WC0559211
Lab Number : 06180874
Unique Number : 11032200
Test Package : MOB1+

Received : 15 May 2024
Tested : 16 May 2024
Diagnosed : 16 May 2024 - Wes Davis

To discuss this sample report, contact Customer Service at 1-800-237-1369.
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

LIBERTY DISPOSAL
6401 S EASTERN AVE
OKLAHOMA CITY, OK
US 73149
Contact: M Rutherford
M.Rutherford@ldi89.com
T:
F: