OIL ANALYSIS REPORT

Sample Rating Trend



NORMAL

Machine Id
KOMATSU WA600-6 6529
Component
Front Left Differential
Fluid
TULCO LUBSOIL TO-4 50 (--- GAL)

DIAGNOSIS

Recommendation
Resample at the next service interval to monitor.

Wear
All component wear rates are normal.

Contamination
There is no indication of any contamination in the oil.

Fluid Condition
The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**TO10003601**	TO10003149	TO10002726
Sample Date		Client Info		**13 Jun 2024**	20 Feb 2024	18 Oct 2023
Machine Age	hrs	Client Info		**22846**	22323	21834
Oil Age	hrs	Client Info		**2091**	1568	1079
Oil Changed		Client Info		**Not Changd**	Not Changd	Not Changd
Sample Status				**NORMAL**	NORMAL	NORMAL

CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method	>.2	**NEG**	NEG	NEG

WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184		**54**	55	20
Iron	ppm	ASTM D5185m	>500	**68**	45	13
Chromium	ppm	ASTM D5185m	>10	**<1**	1	<1
Nickel	ppm	ASTM D5185m	>10	**0**	0	0
Titanium	ppm	ASTM D5185m		**0**	0	0
Silver	ppm	ASTM D5185m		**0**	0	0
Aluminum	ppm	ASTM D5185m	>25	**2**	2	2
Lead	ppm	ASTM D5185m	>25	**0**	<1	0
Copper	ppm	ASTM D5185m	>100	**<1**	0	<1
Tin	ppm	ASTM D5185m	>10	**0**	0	0
Vanadium	ppm	ASTM D5185m		**0**	0	0
Cadmium	ppm	ASTM D5185m		**0**	0	0

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		**0**	0	0
Barium	ppm	ASTM D5185m		**0**	0	0
Molybdenum	ppm	ASTM D5185m		**0**	0	0
Manganese	ppm	ASTM D5185m		**<1**	<1	<1
Magnesium	ppm	ASTM D5185m		**16**	19	20
Calcium	ppm	ASTM D5185m		**4530**	4221	4263
Phosphorus	ppm	ASTM D5185m		**889**	844	882
Zinc	ppm	ASTM D5185m		**1050**	1075	1076
Sulfur	ppm	ASTM D5185m		**5480**	4747	4791

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>75	**17**	17	15
Sodium	ppm	ASTM D5185m		**4**	0	2
Potassium	ppm	ASTM D5185m	>20	**0**	0	<1

FLUID DEGRADATION		method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		**0.92**	0.87	0.83

OIL ANALYSIS REPORT









VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Precipitate	scalar	*Visual	NONE	**NONE**	NONE	NONE
Silt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Debris	scalar	*Visual	NONE	**NONE**	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Appearance	scalar	*Visual	NORML	**NORML**	NORML	NORML
Odor	scalar	*Visual	NORML	**NORML**	NORML	NORML
Emulsified Water	scalar	*Visual	>.2	**NEG**	NEG	NEG
Free Water	scalar	*Visual		**NEG**	NEG	NEG

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445		**200**	200	201
Visc @ 100°C	cSt	ASTM D445		**17.3**	17.5	17.5
Viscosity Index (VI)	Scale	ASTM D2270		**92**	94	93

SAMPLE IMAGES	method	limit/base	current	history1	history2
Color				*no image*	*no image*
Bottom				*no image*	*no image*

GRAPHS

















Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : TO10003601
Lab Number : 06213635
Unique Number : 11086499
Test Package : MOB 2 (Additional Tests: KV100, PQ, VI)

Received : 18 Jun 2024
Tested : 20 Jun 2024
Diagnosed : 20 Jun 2024 - Wes Davis

To discuss this sample report, contact Customer Service at 1-800-237-1369.
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

ANCHOR STONE TULSA ROCK
TULSA ROCK QUARRY, 66TH ST N 145TH AVENUE
TULSA, OK
US 74137
Contact: SKIP SAENGERHAUSEN
skip@anchorstoneco.com
T: (918)928-4575
F: