OIL ANALYSIS REPORT

Area
COLORADO/443/EG - EXCAVATOR
Machine Id
20.144L [COLORADO^443^EG - EXCAVATOR]
Component
Right Final Drive
Fluid
MOBIL MOBILTRANS HD 50 (1 GAL)

Sample Rating Trend



NORMAL

DIAGNOSIS

Recommendation
Resample at the next service interval to monitor.

Wear
All component wear rates are normal.

Contamination
There is no indication of any contamination in the oil.

Fluid Condition
The condition of the oil is acceptable for the time in service.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**WC0928752**	WC0883922	WC0859580
Sample Date		Client Info		**18 Jun 2024**	03 Apr 2024	04 Dec 2023
Machine Age	hrs	Client Info		**4266**	4079	3788
Oil Age	hrs	Client Info		**187**	0	2190
Oil Changed		Client Info		**Not Changd**	Changed	Not Changd
Sample Status				**NORMAL**	NORMAL	NORMAL

CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method	>0.2	**NEG**	NEG	NEG

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>800	**16**	53	39
Chromium	ppm	ASTM D5185m	>10	**0**	<1	<1
Nickel	ppm	ASTM D5185m	>5	**0**	0	0
Titanium	ppm	ASTM D5185m	>15	**<1**	<1	<1
Silver	ppm	ASTM D5185m	>2	**0**	<1	0
Aluminum	ppm	ASTM D5185m	>75	**2**	4	3
Lead	ppm	ASTM D5185m	>10	**0**	<1	1
Copper	ppm	ASTM D5185m	>75	**0**	<1	<1
Tin	ppm	ASTM D5185m	>8	**<1**	0	0
Vanadium	ppm	ASTM D5185m		**0**	<1	0
Cadmium	ppm	ASTM D5185m		**0**	0	0

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		**3**	<1	1
Barium	ppm	ASTM D5185m		**0**	1	0
Molybdenum	ppm	ASTM D5185m		**0**	2	2
Manganese	ppm	ASTM D5185m		**<1**	<1	<1
Magnesium	ppm	ASTM D5185m		**23**	23	3
Calcium	ppm	ASTM D5185m		**3236**	3252	3188
Phosphorus	ppm	ASTM D5185m		**1142**	1075	920
Zinc	ppm	ASTM D5185m		**1359**	1269	1369
Sulfur	ppm	ASTM D5185m		**16195**	13232	14575

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>400	**9**	15	14
Sodium	ppm	ASTM D5185m		**3**	<1	0
Potassium	ppm	ASTM D5185m	>20	**2**	4	2

VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Precipitate	scalar	*Visual	NONE	**NONE**	NONE	NONE
Silt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Debris	scalar	*Visual	NONE	**NONE**	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Appearance	scalar	*Visual	NORML	**NORML**	NORML	NORML
Odor	scalar	*Visual	NORML	**NORML**	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	**NEG**	NEG	NEG
Free Water	scalar	*Visual		**NEG**	NEG	NEG

OIL ANALYSIS REPORT



FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	195	**193**	191	192

SAMPLE IMAGES	method	limit/base	current	history1	history2
Color			*no image*	*no image*	*no image*
Bottom			*no image*	*no image*	*no image*

GRAPHS







Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : WC0928752
Lab Number : 06217188
Unique Number : 11090052
Test Package : CONST

Received : 21 Jun 2024
Tested : 24 Jun 2024
Diagnosed : 24 Jun 2024 - Wes Davis

To discuss this sample report, contact Customer Service at 1-800-237-1369.
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

SHERWOOD CONSTRUCTION CO INC
3219 WEST MAY ST
WICHITA, KS
US 67213
Contact: DOUG KING
doug.king@sherwood.net
T: (316)617-3161
F: x:

Report Id: SHEWIC [WUSCAR] 06217188 (Generated: 06/24/2024 15:02:02) Rev: 1

Submitted By: BRANDEN JAQUIAS