KIMBRO FLUID SOLUTIONS

# OIL ANALYSIS REPORT

Sample Rating Trend




NORMAL

Area
## HOTLINE/120 MILL
Machine Id
## EXIT HYD PUMP HEADER 1415-113-1540
Component
**Hydraulic System**
Fluid
**QUAKER CHEMICAL QUINTOLUBRIC 888-46 (--- GAL)**

## DIAGNOSIS

**Recommendation**
Resample at the next service interval to monitor.

**Wear**
All component wear rates are normal.

**Contamination**
There is no indication of any contamination in the oil. The amount and size of particulates present in the system are acceptable.

**Fluid Condition**
The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

| SAMPLE INFORMATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Sample Number | | Client Info | | **KFS0004564** | KFS0004853 | KFS0004625 |
| Sample Date | | Client Info | | **21 Jun 2024** | 22 Mar 2024 | 16 Feb 2024 |
| Machine Age | hrs | Client Info | | **0** | 0 | 0 |
| Oil Age | hrs | Client Info | | **0** | 0 | 0 |
| Oil Changed | | Client Info | | **N/A** | N/A | N/A |
| Sample Status | | | | **NORMAL** | NORMAL | NORMAL |

| CONTAMINATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Water | | WC Method | >0.05 | **NEG** | NEG | NEG |

| WEAR METALS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Iron | ppm | ASTM D5185m | >20 | **0** | <1 | 0 |
| Chromium | ppm | ASTM D5185m | >20 | **0** | <1 | 0 |
| Nickel | ppm | ASTM D5185m | >20 | **0** | <1 | 0 |
| Titanium | ppm | ASTM D5185m | | **0** | <1 | 0 |
| Silver | ppm | ASTM D5185m | | **0** | 0 | 0 |
| Aluminum | ppm | ASTM D5185m | >20 | **0** | 3 | 0 |
| Lead | ppm | ASTM D5185m | >20 | **0** | <1 | 0 |
| Copper | ppm | ASTM D5185m | >20 | **0** | <1 | 0 |
| Tin | ppm | ASTM D5185m | >20 | **283** | 318 | 274 |
| Vanadium | ppm | ASTM D5185m | | **0** | <1 | 0 |
| Cadmium | ppm | ASTM D5185m | | **0** | <1 | 0 |

| ADDITIVES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Boron | ppm | ASTM D5185m | | **0** | 0 | 0 |
| Barium | ppm | ASTM D5185m | | **0** | <1 | 1 |
| Molybdenum | ppm | ASTM D5185m | | **0** | <1 | 0 |
| Manganese | ppm | ASTM D5185m | | **0** | <1 | 0 |
| Magnesium | ppm | ASTM D5185m | | **0** | <1 | <1 |
| Calcium | ppm | ASTM D5185m | | **8** | 8 | <1 |
| Phosphorus | ppm | ASTM D5185m | | **109** | 107 | 100 |
| Zinc | ppm | ASTM D5185m | | **0** | 1 | 6 |
| Sulfur | ppm | ASTM D5185m | | **710** | 566 | 460 |

| CONTAMINANTS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Silicon | ppm | ASTM D5185m | >15 | **1** | 2 | <1 |
| Sodium | ppm | ASTM D5185m | | **2** | 0 | <1 |
| Potassium | ppm | ASTM D5185m | >20 | **0** | <1 | 0 |

| FLUID CLEANLINESS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Particles >4µm | | ASTM D7647 | >5000 | **691** | 3846 | 3924 |
| Particles >6µm | | ASTM D7647 | >1300 | **102** | 201 | 89 |
| Particles >14µm | | ASTM D7647 | >160 | **10** | 5 | 5 |
| Particles >21µm | | ASTM D7647 | >40 | **3** | 2 | 3 |
| Particles >38µm | | ASTM D7647 | >10 | **0** | 0 | 2 |
| Particles >71µm | | ASTM D7647 | >3 | **0** | 0 | 2 |
| Oil Cleanliness | | ISO 4406 (c) | >19/17/14 | **17/14/10** | 19/15/10 | 19/14/10 |

| FLUID DEGRADATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Acid Number (AN) | mg KOH/g | ASTM D8045 | 2.0 | **1.55** | 1.67 | 1.61 |

# OIL ANALYSIS REPORT













| VISUAL | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| White Metal | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Yellow Metal | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Precipitate | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Silt | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Debris | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Sand/Dirt | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Appearance | scalar | *Visual | NORML | **NORML** | NORML | NORML |
| Odor | scalar | *Visual | NORML | **NORML** | NORML | NORML |
| Emulsified Water | scalar | *Visual | >0.05 | **NEG** | NEG | NEG |
| Free Water | scalar | *Visual | | **NEG** | NEG | NEG |

| FLUID PROPERTIES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Visc @ 40°C | cSt | ASTM D445 | 47.5 | **47.7** | 48.3 | 48.5 |

| SAMPLE IMAGES | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|
| Color | | | | | |
| Bottom | | | | | |



## GRAPHS
















ANAB ACCREDITED ISO/IEC 17025 TESTING LABORATORY
Certificate L2367

**Laboratory** : WearCheck USA - 501 Madison Ave., Cary, NC 27513
**Sample No.** : KFS0004564
**Lab Number** : 06219634
**Unique Number** : 11097831
**Test Package** : IND 2

**Received** : 25 Jun 2024
**Tested** : 26 Jun 2024
**Diagnosed** : 26 Jun 2024 - Don Baldridge

*To discuss this sample report, contact Customer Service at 1-800-237-1369.*
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
*Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)*


**CONSTELLIUM**
4805 SECOND STREET
MUSCLE SHOALS, AL
US 35661
Contact: Joel Even
joel.even@constellium.com
T: (256)740-7490
F: