OIL DIAGNOSTICS

OIL ANALYSIS REPORT

Sample Rating Trend



ISO

Machine Id
BLENDER 2
Component
Gearbox
Fluid
MOBIL SHC 630 (15 GAL)

DIAGNOSIS

Recommendation
We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor.

Wear
All component wear rates are normal.

Contamination
There is a high amount of silt (particulates < 14 microns in size) present in the oil.

Fluid Condition
The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in service.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**PCA0113567**	PCA0103584	PCA0094144
Sample Date		Client Info		**15 Jan 2024**	29 Sep 2023	18 Jul 2023
Machine Age	hrs	Client Info		**0**	0	0
Oil Age	hrs	Client Info		**0**	0	0
Oil Changed		Client Info		**N/A**	N/A	N/A
Sample Status				**ABNORMAL**	ABNORMAL	NORMAL

CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method	>0.2	**NEG**	NEG	NEG

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	**2**	5	1
Chromium	ppm	ASTM D5185m	>15	**0**	<1	0
Nickel	ppm	ASTM D5185m	>15	**0**	0	0
Titanium	ppm	ASTM D5185m		**0**	0	0
Silver	ppm	ASTM D5185m		**0**	0	0
Aluminum	ppm	ASTM D5185m	>25	**0**	2	<1
Lead	ppm	ASTM D5185m	>100	**0**	0	0
Copper	ppm	ASTM D5185m	>200	**0**	<1	<1
Tin	ppm	ASTM D5185m	>25	**<1**	0	0
Vanadium	ppm	ASTM D5185m		**0**	0	<1
Cadmium	ppm	ASTM D5185m		**0**	0	0

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		**0**	0	0
Barium	ppm	ASTM D5185m		**0**	0	0
Molybdenum	ppm	ASTM D5185m		**0**	<1	0
Manganese	ppm	ASTM D5185m		**<1**	<1	0
Magnesium	ppm	ASTM D5185m		**2**	<1	<1
Calcium	ppm	ASTM D5185m		**3**	1	0
Phosphorus	ppm	ASTM D5185m		**455**	438	504
Zinc	ppm	ASTM D5185m		**0**	0	0
Sulfur	ppm	ASTM D5185m		**525**	585	669

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	**23**	27	23
Sodium	ppm	ASTM D5185m		**0**	2	<1
Potassium	ppm	ASTM D5185m	>20	**<1**	<1	0

FLUID CLEANLINESS		method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>10000	▲ **48139**	▲ 91910	556
Particles >6µm		ASTM D7647	>2500	▲ **6941**	▲ 24753	63
Particles >14µm		ASTM D7647	>640	**220**	▲ 1633	6
Particles >21µm		ASTM D7647	>160	**46**	▲ 394	1
Particles >38µm		ASTM D7647	>40	**2**	14	0
Particles >71µm		ASTM D7647	>10	**0**	3	0
Oil Cleanliness		ISO 4406 (c)	>20/18/16	▲ **23/20/15**	▲ 24/22/18	16/13/10

FLUID DEGRADATION		method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		**0.43**	0.54	0.53

OIL ANALYSIS REPORT

OIL DIAGNOSTICS

Particle Trend



Particle Trend



Acid Number



Viscosity @ 40°C



VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Precipitate	scalar	*Visual	NONE	**NONE**	NONE	NONE
Silt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Debris	scalar	*Visual	NONE	**LIGHT**	LIGHT	NONE
Sand/Dirt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Appearance	scalar	*Visual	NORML	**NORML**	NORML	NORML
Odor	scalar	*Visual	NORML	**NORML**	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	**NEG**	NEG	NEG
Free Water	scalar	*Visual		**NEG**	NEG	NEG

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	217.7	**217**	216	217

SAMPLE IMAGES	method	limit/base	current	history1	history2
Color					
Bottom					

GRAPHS

Ferrous Alloys



Non-ferrous Metals



Viscosity @ 40°C



Particle Count



Acid Number



Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : PCA0113567 **Recieved** : 18 Jan 2024
Lab Number : 06064326 **Diagnosed** : 21 Jan 2024
Unique Number : 10835708 **Diagnostician** : Don Baldridge
Test Package : IND 2 (Additional Tests: PrtCount)

To discuss this sample report, contact Customer Service at 1-800-237-1369.
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

KraftHeinz - New Ulm - Plant 8302
2525 S BRIDGE STREET
NEW ULM, MN
US 56073
Contact: RYAN SCHMID
ryan.schmid@kraftheinz.com
T: (507)568-0338
F: (507)354-7927