


## **VOLVO L90 62625**

Diesel Engine

Diesel Engine  Fluid  MOBIL 15W40 ( GAL)							
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		VCP34011		
	Sample Date		Client Info		03 Aug 2006		
	Machine Age	hrs	Client Info		70770		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Changed		
	Filter Changed		Client Info		Changed		
	Sample Status				NORMAL		
WEAR	Iron	ppm	ASTM D5185m		41		
	Chromium	ppm	ASTM D5185m		<1		
All component wear rates are normal.	Nickel	ppm	ASTM D5185m		2		
	Titanium	ppm	ASTM D5185m		0		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m		5		
	Lead	ppm	ASTM D5185m		4		
	Copper	ppm	ASTM D5185m		3		
	Tin	ppm	ASTM D5185m		1		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m		4		
There is no indication of any contamination in the component.	Potassium	ppm	ASTM D5185m		<1		
	Fuel		WC Method		<1.0		
	Water		WC Method		NEG		
	Glycol		WC Method		NEG		
	Soot %	%	*ASTM D7844		0.5		
	Nitration	Abs/cm			0.00		
	Sulfation	Abs/.1mm			0.05		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML NEG		
<u></u>	Emulsified Water	Scalai	*Visual		NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m		<1		
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m		6		
	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m		12		
	Manganese	ppm	ASTM D5185m		2		
	Magnesium	ppm	ASTM D5185m		242		
	Calcium	ppm	ASTM D5185m		2196		
	Phosphorus	ppm	ASTM D5185m		1000		
	Zinc	ppm	ASTM D5185m		1095		
	Sulfur	ppm	ASTM D5185m		5756		
	Oxidation	Abs/.1mm	*ASTM D7414		0.05		
	Visc @ 100°C	cSt	ASTM D445		14.5		





Certificate L2367

Laboratory Sample No.

: VCP34011 Lab Number : 01799188 Unique Number : 3836601 Test Package : MOB 1

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 07 Aug 2006 **Tested** : 08 Aug 2006

Diagnosed

BALTIMORE, MD US 21227 Contact: MARK CIULLA

MCCLUNG-LOGAN EQUIPMENT CO - BALTIMORE

4601 WASHINGTON BOULEVARD

mciulla@mcclung-logan.com T: (410)242-6500

To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: (410)242-7835