WEAR CONTAMINATION FLUID CONDITION **NORMAL NORMAL NORMAL**

REGION OF WATERLOO [388565]

VOLVO L120H 833154

Component Diesel Engine

VOI VO III TRA DIESEI ENGINE OIL 15W40 VDS-3 (--- GAL)

VOLVO ULTRA DIESEL ENGINE OIL 15W40 VDS-3 (GAL)							
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		VCP394556		
	Sample Date		Client Info		11 Jan 2024		
	Machine Age	hrs	Client Info		4039		
	Oil Age	hrs	Client Info		500		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Changed		
	Filter Changed		Client Info		Changed		
	Sample Status				NORMAL		
WEAR	Iron	ppm	ASTM D5185(m)	>100	12		
All component wear rates are normal.	Chromium	ppm	ASTM D5185(m)	>10	<1		
7. II component treat rates are normal.	Nickel	ppm	ASTM D5185(m)	>10	<1		
	Titanium	ppm	ASTM D5185(m)		0		
	Silver	ppm	ASTM D5185(m)	>2	0		
	Aluminum	ppm	ASTM D5185(m)	>10	7		
	Lead	ppm	ASTM D5185(m)	>20	<1		
	Copper	ppm	ASTM D5185(m)	>15	1		
	Tin	ppm	ASTM D5185(m)	>10	<1		
	Vanadium	ppm	ASTM D5185(m)		0		
CONTAMINATION	Ciliana		ACTM DE10E()	00			
	Silicon Potassium	ppm	ASTM D5185(m) ASTM D5185(m)		7 <1		
There is no indication of any contamination in the oil.	Fuel	ppm	WC Method		<1.0		
	Water		WC Method		NEG		
	Glycol		WC Method	>0.1	NEG		
	Soot %	%	ASTM D7844*	>3	0.4		
	Nitration	Abs/cm	ASTM D7624*	>20	7.7		
	Sulfation	Abs/.1mm	ASTM D7415*		23.5		
	Emulsified Water	scalar	Visual*	>0.1	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185(m)		2		
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185(m)	2.5	29		
	Barium	ppm	ASTM D5185(m)	0.0	0		
	Molybdenum	ppm		0.7	40		
	Manganese	ppm	ASTM D5185(m)	0.0	0		
	Magnesium	ppm	ASTM D5185(m)	256	509		
	Calcium	ppm	ASTM D5185(m)	2057	1752		
	Phosphorus	ppm	ASTM D5185(m)	935	928		
	Zinc	ppm	ASTM D5185(m)	1223	1084		
	Sulfur	ppm	ASTM D5185(m)	4079	2499		
	Oxidation	Abs/.1mm	ASTM D7414*	>25	21.2		
	Visc @ 100°C	cSt		15.0	13.1		
				_			





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No. Lab Number

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 : VCP394556 : 02610547 Unique Number : 5711633

Recieved Diagnosed Test Package : MOB 1

: 23 Jan 2024 Diagnostician : Wes Davis

: 23 Jan 2024

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

Strongco Equipment 5179 Fountain St N.

Breslau, ON CA N0B 1M0 Contact: Eric Mailloux emailloux@strongco.com T: (519)744-3518

F: (519)744-3284