



OIL ANALYSIS REPORT

WEAR	NORMAL
CONTAMINATION	NORMAL
FLUID CONDITION	NORMAL







Area
(C-GSWK) PERIMETER AVIATION [53028]
 Machine Id
[C-GSWK] FAIRCHILD SA226TC P-54108 (S/N TC-368)
 Component
2 Jet Turbine
 Fluid
EASTMAN TURBO OIL 2380 (--- GAL)

RECOMMENDATION

Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		GT57290	GT53408	GT53409
Sample Date		Client Info		25 Feb 2024	18 May 2021	09 Apr 2021
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		17	303	206
Filter Age	hrs	Client Info		17	98	94
Oil Changed		Client Info		N/A	N/A	N/A
Filter Changed		Client Info		N/A	N/A	N/A
Sample Status				---	---	NORMAL
Water		WC Method	>0.1	NEG	NEG	NEG
Acid Number (AN)	mg KOH/g	ASTM D974*	0.43	0.60	0.16	0.14
Visc @ 40°C	cSt	ASTM D7279(m)	24.2	24.5	---	---

WEAR

CONTAMINATION



Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : GT57290
Lab Number : 02619449
Unique Number : 5736559
Test Package : G331

Received : 01 Mar 2024
Tested :
Diagnosed :

Honeywell Engines
 111 S. 34th Street, 301 Receiving, Attn: SOAP Program
 PHOENIX, AZ
 US 85034
 Contact: GARRETT

To discuss this sample report, contact Customer Service at 1-800-268-2131.
 Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
 Validity of results and interpretation are based on the sample and information as supplied.

T:
 F: (602)365-2676