

## NORMAL WEAR CONTAMINATION MARGINAL **FLUID CONDITION ABNORMAL**

Machine Id 801028 nponer

**Diesel Engine** PETRO CANADA DURON SHP 15W40 (19 LTR)

.....

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor.

	-	_	_	-	-	_	-	_	_	-	-	_	-	_	_	-	_	_	-	_	_	-	-	_	-	-	
							-		-																		
		T.	٧	1			Λ	V	E	2																	
		V	Ľ		-	7	1	4		Ц																	
l		_	_	_		_		_						_			_			_							

RECOMMENDATION

All component wear rates are normal.

## CONTAMINATION


Light fuel dilution occurring.

## **FLUID CONDITION**

Fuel is present in the oil and is lowering the viscosity. The condition of the oil is acceptable for the time in service.

1	5W40 (19 L	- I R)					
	Test	UOM	Method	Limit/Abn	Current	History1	History2
	Sample Number		Client Info		GFL0117917	GFL0107123	GFL0094187
	Sample Date		Client Info		01 Apr 2024	18 Jan 2024	01 Nov 2023
	Machine Age	hrs	Client Info		15552	15552	9432
	Oil Age	hrs	Client Info		600	0	0
	Filter Age	hrs	Client Info		600	0	0
	Oil Changed		Client Info		Changed	Changed	Changed
	Filter Changed		Client Info		Changed	Changed	N/A
	Sample Status				ABNORMAL	NORMAL	NORMAL
	Iron			. 00	 00	01	
	Iron	ppm	ASTM D5185(m)	>80	23	21	29
	Chromium Nickel	ppm	ASTM D5185(m)	>5	<1	<1	<1
		ppm	ASTM D5185(m)	>2	0	<1	<1
	Titanium Silver	ppm	ASTM D5185(m)	. 0	0	0	0
		ppm	ASTM D5185(m)	>3	0	0	<1 3
	Aluminum	ppm	ASTM D5185(m)	>30	2	2	
	Lead	ppm	ASTM D5185(m)	>30	0	<1	<1
	Copper	ppm	ASTM D5185(m)	>150	<1	<1	1
	Tin	ppm	ASTM D5185(m)	>5	0	0	0
	Vanadium	ppm	ASTM D5185(m)		0	0	0
	Silicon	ppm	ASTM D5185(m)	>20	2	4	5
	Potassium	ppm	ASTM D5185(m)	>20	1	2	1
	Fuel	%	ASTM D7593*	>5	<b>4</b> .8	<1.0	<1.0
	Water		WC Method	>0.2	NEG	NEG	NEG
	Glycol		WC Method		NEG	NEG	NEG
	Soot %	%	ASTM D7844*	>3	0.3	0.3	0.4
	Nitration	Abs/cm	ASTM D7624*	>20	10.5	10.1	11.0
	Sulfation	Abs/.1mm	ASTM D7415*	>30	21.4	21.4	22.9
	Emulsified Water	scalar	Visual*	>0.2	NEG	NEG	NEG
	Sodium	ppm	ASTM D5185(m)		9	10	10
	Boron	ppm	ASTM D5185(m)	0	7	10	10
	Barium	ppm	ASTM D5185(m)	0	0	0	<1
	Molybdenum	ppm	ASTM D5185(m)	60	60	63	67
	Manganese	ppm	ASTM D5185(m)	0	<1	0	0
	Magnesium	ppm	ASTM D5185(m)	1010	954	969	995
	Calcium	ppm	ASTM D5185(m)	1070	1046	1125	1156
	Phosphorus	ppm	ASTM D5185(m)	1150	968	1036	1039
	Zinc	ppm	ASTM D5185(m)	1270	1182	1222	1297
	Sulfur	ppm	ASTM D5185(m)	2060	2356	2606	2483
	Oxidation	Abs/.1mm	ASTM D7414*	>25	18.5	17.7	19.8
	Visc @ 100°C	cSt	ASTM D7279(m)	15.4	<b>12.9</b>	14.1	14.2
					$\sim$		

Submitted By: Scott Ewan



: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9

Received

Diagnosed

Tested

Test Package : MOB 1 (Additional Tests: FuelDilution, PercentFuel)

Validity of results and interpretation are based on the sample and information as supplied.

: 12 Apr 2024

: 15 Apr 2024

GFL Environmental - 217 - Aurora 14131 BAYVIEW AVE, AURORA YARD AURORA, ON : 15 Apr 2024 - Wes Davis CA L4G 0K6 Contact: Mike Havens MHavens@gflenv.com Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab. T: F: (905)713-2445

CALA

ISO 17025:2017

Accredited

Laboratory

Laboratory

Sample No.

Lab Number : 02628324

Unique Number : 5761456

: GFL0117917

To discuss this sample report, contact Customer Service at 1-800-268-2131.

% fuel

Œ

Submitted By: Scott Ewan Page 2 of 2

Jan 18/24

lav15/23

/av15/23

May15/23

Anr6/20

Jan 18/24

Jan 18/24

nr6/20

Jav31/19