WEAR CONTAMINATION **FLUID CONDITION**

NORMAL NORMAL NORMAL

Machine Id

WIRTGEN 266-0801

Front Left Final Drive

RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.	Sample Number		Client Info		PC0088725		
	Sample Date		Client Info		05 May 2024		
	Machine Age	hrs	Client Info		7880		
	Oil Age	hrs	Client Info		500		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Changed		
	Filter Changed		Client Info		N/A		
	Sample Status				NORMAL		
WEAR	Iron	nnm	ASTM D5185(m)	<u> 500</u>	7		
WLAN	Chromium	ppm	ASTM D5185(III) ASTM D5185(m)		0		
All component wear rates are normal.	Nickel	ppm	ASTM D5185(m)		0		
	Titanium	ppm	ASTM D5185(m)	>10	0		
	Silver	ppm	ASTM D5185(m)		0		
	Aluminum	ppm	ASTM D5185(III) ASTM D5185(m)	>25	0		
	Lead	ppm	ASTM D5185(m)		<1		
	Copper	ppm	ASTM D5185(m)		<1		
	Tin	ppm	ASTM D5185(m)		0		
	Vanadium	ppm	ASTM D5185(m)		0		
	White Metal	scalar	Visual*	NONE	VLITE		
	Yellow Metal	scalar	Visual*	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185(m)	>75	25		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185(m)	>20	<1		
	Water		WC Method	>0.2	NEG		
	Silt	scalar	Visual*	NONE	NONE		
	Debris	scalar	Visual*	NONE	NONE		
	Sand/Dirt	scalar	Visual*	NONE	NONE		
	Appearance	scalar	Visual*	NORML	NORML		
	Odor	scalar	Visual*	NORML	NORML		
	Emulsified Water	scalar	Visual*	>0.2	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185(m)		<1		
The oil viscosity is higher than typical. The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185(m)		2		
	Barium	ppm	ASTM D5185(m)		0		
	Molybdenum	ppm	ASTM D5185(m)		0		
	Manganese	ppm	ASTM D5185(m)		0		
	Magnesium	ppm	ASTM D5185(m)		<1		
	Calcium	ppm	ASTM D5185(m)		<1		
	Phosphorus	ppm	ASTM D5185(m)		431		
	Zinc	ppm	ASTM D5185(m)		1		
	Sulfur	ppm	ASTM D5185(m)		155		
	Visc @ 40°C	cSt	ASTM D7279(m)	220	222		
	Visc @ 100°C	cSt	ASTM D7279(m)	18.5	29.3		
	Viscosity Index (VI)	Scale	ASTM D2270*	93	171		





CALA ISO 17025:2017 Accredited

Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Sample No. : PC0088725 Received Lab Number : 02635761 **Tested**

: 15 May 2024

: 15 May 2024

: 15 May 2024 - Kevin Marson Unique Number : 5776914 Diagnosed Laboratory Test Package : MOB 1 (Additional Tests: KV100, VI)

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

LAVIS CONTRACTING 37462A HURON ROAD CLINTON, ON CA NOM 1L0 Contact: Doug Francis dfrancis@lavis.ca T: (519)482-3694 F: (519)482-7886