WEAR CONTAMINATION FLUID CONDITION

NORMAL NORMAL NORMAL



Machine Id **LIEBHERR LH50M 151293-1216**

Front Differential

Front Differential GEAR OIL SAE 80W90 (GAL))				.,		
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80W90. Please confirm.	Sample Number		Client Info		LH0290910		
	Sample Date		Client Info		21 May 2024		
	Machine Age	hrs	Client Info		1496		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Changed		
	Filter Changed		Client Info		N/A		
	Sample Status				NORMAL		
WEAR	Iron	ppm	ASTM D5185(m)	>190	4		
All component wear rates are normal.	Chromium	ppm	ASTM D5185(m)		0		
	Nickel	ppm	ASTM D5185(m)		0		
	Titanium	ppm	ASTM D5185(m)		0		
	Silver	ppm	ASTM D5185(m)		0		
	Aluminum	ppm	ASTM D5185(m)	>5	0		
	Lead	ppm	ASTM D5185(m)		<1		
	Copper	ppm	ASTM D5185(m)	>70	24		
	Tin	ppm	ASTM D5185(m)	>2	0		
	Vanadium	ppm	ASTM D5185(m)		0		
	White Metal	scalar	Visual*	NONE	NONE		
	Yellow Metal	scalar	Visual*	NONE	NONE		
CONTAMINATION There is no indication of any contamination in the oil.	Silicon	ppm	ASTM D5185(m)	>20	2		
	Potassium	ppm	ASTM D5185(m)	>20	<1		
	Water		WC Method	>.2	NEG		
	Silt	scalar	Visual*	NONE	NONE		
	Debris	scalar	Visual*	NONE	VLITE		
	Sand/Dirt	scalar	Visual*	NONE	NONE		
	Appearance	scalar	Visual*	NORML	NORML		
	Odor	scalar	Visual*	NORML	NORML		
	Emulsified Water	scalar	Visual*	>.2	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185(m)	>170	3		
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185(m)	400	137		
	Barium	ppm	ASTM D5185(m)	200	4		
	Molybdenum	ppm	ASTM D5185(m)	12	0		
	Manganese	ppm	ASTM D5185(m)		<1		
	Magnesium	ppm	ASTM D5185(m)	12	1		
	Calcium	ppm	ASTM D5185(m)	150	5		
	Phosphorus	ppm	ASTM D5185(m)	1650	1747		
	Zinc	ppm		125	20		
	Sulfur	ppm	ASTM D5185(m)		33382		
	Visc @ 40°C	cSt	ASTM D7279(m)	143	139		





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No.

Lab Number : 02636994 Unique Number : 5786156

Test Package : MOB 1

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 : LH0290910 Received

: 22 May 2024 **Tested** : 22 May 2024 Diagnosed

: 22 May 2024 - Wes Davis

Contact: Service Manager

1625066 ONTARIO LTD.

870 MACKAY RD

PICKERING, ON

CA L1W 2Y4

T: F:

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.