WEAR CONTAMINATION FLUID CONDITION

NORMAL NORMAL

Area

[405211]

VOLVO L90H 627930

Component Transmission (Auto) Fluid {not provided} (GAL)							
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.	Sample Number		Client Info		VCP393062		
	Sample Date		Client Info		17 May 2024		
	Machine Age	hrs	Client Info		495		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		N/A		
	Filter Changed		Client Info		N/A		
	Sample Status				NORMAL		
WEAR All component wear rates are normal.	Iron	ppm	ASTM D5185(m)	>160	44		
	Chromium	ppm	ASTM D5185(m)		0		
	Nickel	ppm	ASTM D5185(m)		0		
	Titanium	ppm	ASTM D5185(m)		0		
	Silver	ppm	ASTM D5185(m)	>5	0		
	Aluminum	ppm	ASTM D5185(m)	>50	<1		
	Lead	ppm	ASTM D5185(m)	>50	0		
	Copper	ppm	ASTM D5185(m)	>225	5		
	Tin	ppm	ASTM D5185(m)	>10	0		
	Vanadium	ppm	ASTM D5185(m)		0		
	White Metal	scalar	Visual*	NONE	NONE		
	Yellow Metal	scalar	Visual*	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185(m)	>20	6		
There is no indication of any contamination in the fluid.	Potassium	ppm	ASTM D5185(m)	>20	1		
	Water	PPIII	WC Method		NEG		
	Silt	scalar	Visual*	NONE	NONE		
	Debris	scalar	Visual*	NONE	NONE		
	Sand/Dirt	scalar	Visual*	NONE	NONE		
	Appearance	scalar	Visual*	NORML	NORML		
	Odor	scalar	Visual*	NORML	NORML		
	Emulsified Water	scalar	Visual*	>0.1	NEG		
FLUID CONDITION	Sodium	nnm	ASTM D5185(m)		3		
The condition of the fluid is acceptable for the time in service.	Boron	ppm	ASTM D5185(m)		60		
	Barium	ppm	ASTM D5185(m)		1		
	Molybdenum	ppm	ASTM D5185(m)		0		
	Manganese	ppm	ASTM D5185(m)		6		
	Magnesium	ppm	ASTM D5185(m)		2		
	Calcium	ppm	ASTM D5185(m)		70		
	Phosphorus	ppm	ASTM D5185(m)		157		
	Zinc	ppm	ASTM D5185(m)		21		

Sulfur

Visc @ 40°C

1383

28.9

ASTM D5185(m)

ASTM D7279(m)

ppm





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No.

: VCP393062 Lab Number : 02637219 Unique Number : 5786381 Test Package : MOB 1

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Received : 23 May 2024 : 23 May 2024 **Tested** Diagnosed

: 23 May 2024 - Wes Davis

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

STRONGCO EQUIPMENT INC.

72 CHEMIN DU TREMBLAY BOUCHERVILLE, QC CA J4B 6Z6

Contact: Jonathan Lamontagne jlamontagne@strongco.com T: (450)449-4666

F: (450)449-7913