WEAR CONTAMINATION FLUID CONDITION

NORMAL NORMAL



Machine Id LIEBHERR LH50 14799

Front Differential

CHEVRON DELO GEAR ESI OI	L 80W90 (4	LTR)					
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		LH0277068		
	Sample Date		Client Info		08 May 2024		
	Machine Age	hrs	Client Info		17000		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Changed		
	Filter Changed		Client Info		N/A		
	Sample Status				NORMAL		
WEAR	Iron	ppm	ASTM D5185(m)	>190	4		
All component wear rates are normal.	Chromium	ppm	ASTM D5185(m)	>2	0		
	Nickel	ppm	ASTM D5185(m)	>2	<1		
	Titanium	ppm	ASTM D5185(m)		0		
	Silver	ppm	ASTM D5185(m)		0		
	Aluminum	ppm	ASTM D5185(m)	>5	0		
	Lead	ppm	ASTM D5185(m)	>15	0		
	Copper	ppm	ASTM D5185(m)		<1		
	Tin	ppm	ASTM D5185(m)	>2	0		
	Vanadium	ppm	ASTM D5185(m)		0		
	White Metal	scalar	Visual*	NONE	NONE		
	Yellow Metal	scalar	Visual*	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185(m)	>20	0		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185(m)	>20	<1		
	Water		WC Method	>.2	NEG		
	Silt	scalar	Visual*	NONE	NONE		
	Debris	scalar	Visual*	NONE	VLITE		
	Sand/Dirt	scalar	Visual*	NONE	NONE		
	Appearance	scalar	Visual*	NORML	NORML		
	Odor	scalar	Visual*	NORML	NORML		
	Emulsified Water	scalar	Visual*	>.2	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185(m)		<1		
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185(m)	15	302		
	Barium	ppm	ASTM D5185(m)	0	0		
	Molybdenum	ppm	ASTM D5185(m)	0	3		
	Manganese	ppm	ASTM D5185(m)		0		
	Magnesium	ppm	ASTM D5185(m)		3		
	Calcium	ppm	ASTM D5185(m)		19		
	Phosphorus	ppm	ASTM D5185(m)	600	1556		
	Zinc	ppm	ASTM D5185(m)		13		
	Sulfur	ppm	ASTM D5185(m)	22000	18415		
Report Id: BATRRI I IWCAMISI 02637276 (Generated: 05/23/2024 16:30:06) Rev: 1	Visc @ 40°C	cSt	ASTM D7279(m)	140	128	 mial Haaba	 DATDDII





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No.

: LH0277068 Lab Number : 02637276 Unique Number : 5786438 Test Package : MOB 1

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Received : 23 May 2024 **Tested** : 23 May 2024

Diagnosed : 23 May 2024 - Wes Davis

To discuss this sample report, contact Customer Service at 1-800-268-2131.

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

INTERFOR CORP

5060 RTE 430 BRUNSWICK MINE, NB CA E2A 6W6

Contact: Daniel Hachey daniel.hachey@interfor.com T: (506)547-8700

F: (506)548-1892