Honeywell

OIL ANALYSIS REPORT

Area SKYCARE AIR AMBULANCE [53371] FAIRCHILD SA227 P-44470C (S/N AC632)

Right Jet Turbine

EASTMAN TURBO OIL 2380 (--- GAL)

RECOMMENDATION


This is a baseline read-out on the submitted sample.

\mathbf{H}	

CONTAMINATION
FLUID CONDITION

Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		GT58021	GT57808	GT57806
Sample Date		Client Info		07 Jun 2024	19 May 2024	07 May 2024
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		243	170	111
Filter Age	hrs	Client Info		73	60	72
Oil Changed		Client Info		N/A	N/A	N/A
Filter Changed		Client Info		N/A	N/A	N/A
Sample Status				NORMAL	NORMAL	
Iron	ppm	ASTM D5185(m)	>8	0	0	0
Chromium	ppm	ASTM D5185(m)	>2	0	0	0
Nickel	ppm	ASTM D5185(m)	>2	0	0	0
Silver	ppm	ASTM D5185(m)	>2	0	0	0
Aluminum	ppm	ASTM D5185(m)	>2	<1	<1	<1
Lead	ppm	ASTM D5185(m)	>3	0	<1	<1
Copper	ppm	ASTM D5185(m)	>3	<1	0	0
Water		WC Method	>0.1	NEG	NEG	NEG
Magnesium	ppm	ASTM D5185(m)	0	0	0	0
Acid Number (AN)	mg KOH/g	ASTM D974*	0.43	0.54	0.58	0.53
Visc @ 40°C	cSt	ASTM D7279(m)	24.2	24.3	23.9	

WEAR NORMAL CONTAMINATION NORMAL FLUID CONDITION NORMAL



Report Id: HONPHO [WCAMIS] 02641558 (Generated: 06/12/2024 16:28:56) Rev: 1

Contact/Location: GARRETT ? - HONPHO Page 2 of 2