WEAR CONTAMINATION **FLUID CONDITION**

NORMAL NORMAL NORMAL

Area
KANSAS/44

45.61L [KANSAS^44]

Component Transmission (Auto)

MOBIL MOBILFLUID 424 (GAL)							
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		WC0621129		
Tresumple at the next service interval to monitor.	Sample Date		Client Info		23 Nov 2021		
	Machine Age	hrs	Client Info		10632		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Not Changd		
	Filter Changed		Client Info		Not Changd		
	Sample Status				NORMAL		
WEAR	Iron	ppm	ASTM D5185m	>160	12		
All component wear rates are normal.	Chromium	ppm	ASTM D5185m	>5	<1		
	Nickel	ppm	ASTM D5185m	>5	0		
	Titanium	ppm	ASTM D5185m		0		
	Silver	ppm	ASTM D5185m	>5	<1		
	Aluminum	ppm	ASTM D5185m	>50	<1		
	Lead	ppm	ASTM D5185m	>50	<1		
	Copper	ppm	ASTM D5185m	>225	16		
	Tin	ppm	ASTM D5185m	>10	<1		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	>20	4		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m		0		
	Water			>0.1	NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.1	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m		2		
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m		7		
	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m		<1		
	Manganese	ppm	ASTM D5185m		<1		
	Magnesium	ppm	ASTM D5185m		52		
	Calcium	ppm	ASTM D5185m		3522		
	Phosphorus	ppm	ASTM D5185m		1198		
	Zinc	ppm	ASTM D5185m		1287		
	Sulfur	ppm	ASTM D5185m	55	3617		
	Visc @ 40°C	cSt	ASTM D445	55	48.1		







Report Id: SHEWIC [WUSCAR] 05411386 (Generated: 03/07/2024 16:02:52) Rev: 1

Laboratory Sample No.

Lab Number : 05411386 Unique Number : 9760574 Test Package : MOBCE

To discuss this sample report, contact Customer Service at 1-800-237-1369.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : WC0621129 Received : 29 Nov 2021 **Tested** : 01 Dec 2021

: 01 Dec 2021 - Don Baldridge Diagnosed

SHERWOOD CONSTRUCTION CO INC

3219 WEST MAY ST WICHITA, KS US 67213

Contact: RANDY ROBERTS randy.roberts@sherwood.net

T: (316)943-6491

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: x: