

WEAR CONTAMINATION FLUID CONDITION

ABNORMAL NORMAL NORMAL



Ascendum Machinery VOLVO SD115B R-3 (S/N 236166)

Component Rear Right Planetary

VÖLVO SUPER GEAR OIL 75W-80-GO102 (GAL)							
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
The oil change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor.	Sample Number		Client Info		VCP0001609		
	Sample Date		Client Info		04 Apr 2022		
	Machine Age		Client Info		2515		
	Oil Age		Client Info		2515		
	Filter Age		Client Info		0		
	Oil Changed		Client Info		Changed		
	Filter Changed		Client Info		None		
	Sample Status				ABNORMAL		
WEAR	Iron	ppm	ASTM D5185m	>500	423		
High concentration of visible metal present. All component wear rates are normal.	Chromium	ppm	ASTM D5185m		5		
	Nickel	ppm	ASTM D5185m	>10	1		
	Titanium	ppm	ASTM D5185m		- <1		
	Silver	ppm	ASTM D5185m		<1		
	Aluminum	ppm	ASTM D5185m	>25	7		
	Lead	ppm	ASTM D5185m		0		
	Copper	ppm	ASTM D5185m		2		
	Tin	ppm	ASTM D5185m		- <1		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	▲ HEAVY		
	Yellow Metal	scalar	*Visual	NONE	NONE		
There is no indication of any contamination in the oil.	Silicon	ppm	ASTM D5185m	>75	28		
	Potassium	ppm	ASTM D5185m	>20	0		
	Water		WC Method	>0.2	NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.2	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m		10		
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m		89		
	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m		1		
	Manganese	ppm	ASTM D5185m		29		
	Magnesium	ppm	ASTM D5185m		0		
	Calcium	ppm	ASTM D5185m		55		
	Phosphorus	ppm	ASTM D5185m		2282		
	Zinc	ppm	ASTM D5185m		46		
	Sulfur	ppm	ASTM D5185m		24098		
	Visc @ 40°C	cSt	ASTM D445		101		





Certificate L2367

Laboratory Sample No.

: VCP0001609 Lab Number : 05512361 Unique Number : 9921635 Test Package : MOBCE

To discuss this sample report, contact Customer Service at 1-800-237-1369.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 06 Apr 2022

Tested : 08 Apr 2022 : 08 Apr 2022 - Don Baldridge Diagnosed

CAROLINA EXCAVATING

1036 BRANCHVIEW DR, SUITE 106 CONCORD, NC

> US 28025 Contact: KEVIN LADGERWOOD

kevin@carlinaexcavation.com

T: F:

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)