

[W44830] Machine Id BOMAG BMP8500 101720128961 Component Diesel Engine

{not provided} (--- GAL)

RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition. Please specify the brand, type, and viscosity of the oil on your next sample.	Sample Number		Client Info		JR0147157	JR0041139	
	Sample Date		Client Info		19 Jun 2023	02 Apr 2020	
	Machine Age	hrs	Client Info		471	256	
	Oil Age	hrs	Client Info		221	256	
	Filter Age	hrs	Client Info		221	256	
	Oil Changed		Client Info		Changed	Changed	
	Filter Changed		Client Info		Changed	Changed	
	Sample Status				ABNORMAL	ABNORMAL	
WEAR	Iron	ppm	ASTM D5185m	>100	28	21	
	Chromium	ppm	ASTM D5185m		2	2	
Metal levels are typical for a new component breaking in.	Nickel	ppm	ASTM D5185m		0	0	
	Titanium	ppm	ASTM D5185m	- 1	0	0	
	Silver	ppm	ASTM D5185m	>3	0	0	
	Aluminum	ppm	ASTM D5185m		8	6	
	Lead	ppm	ASTM D5185m		0	<1	
	Copper	ppm	ASTM D5185m		5	11	
	Tin	ppm	ASTM D5185m		5	6	
	Vanadium	ppm	ASTM D5185m	10	<1	0	
	White Metal	scalar	*Visual	NONE	NONE	NONE	
	Yellow Metal	scalar	*Visual	NONE	NONE	NONE	
CONTAMINATION	Silicon	ppm	ASTM D5185m		27	42	
There is a moderate amount of fuel present in the oil. Tests confirm the presence of fuel in the oil.	Potassium	ppm	ASTM D5185m		2	2	
	Fuel	%	ASTM D3524		6 .9	<1.0	
	Water		WC Method	>0.2	NEG	NEG	
	Glycol		WC Method		NEG	NEG	
	Soot %	%	*ASTM D7844		0.1	0.1	
	Nitration	Abs/cm	*ASTM D7624	>20	7.1	5.8	
	Sulfation	Abs/.1mm	*ASTM D7415		19.6	15.6	
	Silt	scalar	*Visual	NONE	NONE	NONE	
	Debris	scalar	*Visual	NONE	NONE	NONE	
	Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	
	Appearance	scalar	*Visual	NORML	NORML	NORML	
	Odor	scalar	*Visual	NORML	NORML	NORML	
	Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	
FLUID CONDITION	Sodium	ppm	ASTM D5185m		3	2	
The BN result indicates that there is suitable alkalinity remaining in the oil. Fuel is present in the oil and is lowering the viscosity. The oil is no longer serviceable due to the presence of contaminants.	Boron	ppm	ASTM D5185m		206	24	
	Barium	ppm	ASTM D5185m		0	5	
	Molybdenum	ppm	ASTM D5185m		185	31	
	Manganese	ppm	ASTM D5185m		<1	2	
	Magnesium	ppm	ASTM D5185m		622	55	
	Calcium	ppm	ASTM D5185m		1649	3184	
	Phosphorus	ppm	ASTM D5185m		775	883	
	Zinc	ppm	ASTM D5185m		965	968	
	0.16.14		AOTA DEADE		0.400	0504	

Sulfur

Oxidation

Visc @ 100°C cSt

ppm ASTM D5185m

Base Number (BN) mg KOH/g ASTM D2896

Abs/.1mm *ASTM D7414 >25

ASTM D445

2504

10.2

11.4


9.3

3400

15.6

8.9

11.5



JRE - ASHLAND Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513 Sample No. : JR0147157 Recieved : 21 Jun 2023 11047 LEADBETTER RD Lab Number : 05879235 Diagnosed : 22 Jun 2023 ASHLAND, VA : 10524338 Unique Number Diagnostician : Wes Davis US 23005 Test Package : CONST (Additional Tests: FuelDilution, PercentFuel, TBN) Contact: DAVID ZIEG Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369. dzieg@jamesriverequipment.com * - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (804)798-6001 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (804)798-0292