**WEAR** CONTAMINATION **FLUID CONDITION** 


**NORMAL ABNORMAL NORMAL** 

Area **FLEET** 

## Machine Id **VOLVO VNR64T640 26631**

Component Front Differential

RECOMMENDATION  No corrective action is recommended at this time. Resample at the next service interval to monitor.	T	11014	NA-AL-	1.597A1		1.15-4. 4	111-7
	Test	UOM	Method	Limit/Abn	Current	History1	History2
	Sample Number		Client Info		PCA0112310 28 Dec 2023		
	Sample Date	mlo	Client Info		350120		
	Machine Age	mls	Client Info		350120		
	Oil Age Filter Age	mls mls	Client Info		0		
	Oil Changed	11113	Client Info		N/A		
	Filter Changed		Client Info		N/A		
	Sample Status				ABNORMAL		
WEAR	Iron	ppm	ASTM D5185m	>500	437		
All component wear rates are normal.	Chromium	ppm	ASTM D5185m	>10	3		
	Nickel	ppm	ASTM D5185m	>10	7		
	Titanium	ppm	ASTM D5185m		0		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m		2		
	Lead	ppm	ASTM D5185m		48		
	Copper	ppm	ASTM D5185m		97		
	Tin	ppm	ASTM D5185m	>10	12		
	Vanadium	ppm	ASTM D5185m	NONE	0		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	>75	<u> </u>		
Elemental level of silicon (Si) above normal indicating ingress of seal material.	Potassium	ppm	ASTM D5185m	>20	4		
	Water		WC Method	>.2	NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>.2	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m		10		
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m	400	140		
	Barium	ppm	ASTM D5185m	200	0		
	Molybdenum	ppm	ASTM D5185m	12	0		
	Manganese	ppm	ASTM D5185m		13		
	Magnesium	ppm	ASTM D5185m	12	2		
	Calcium	ppm	ASTM D5185m	150	77		
	Phosphorus	ppm	ASTM D5185m	1650	1440		
	Zinc	ppm	ASTM D5185m	125	54		
	Sulfur	ppm	ASTM D5185m	22500	21966		
						•	







Laboratory Sample No. Lab Number

**Unique Number** 

: PCA0112310 : 06058419 : 10829801

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Recieved : 11 Jan 2024 Diagnosed : 14 Jan 2024 Diagnostician : Don Baldridge

Test Package : FLEET Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

**PERDUE FARMS - DILLON** 

2047 HWY 9 WEST DILLON, SC US 29536

Contact: KEVIN HOOKS kevin.hooks@perdue.com T: (843)841-8069

Submitted By: KEVIN HOOKS

F: (843)841-8070