WEAR CONTAMINATION FLUID CONDITION


NORMAL NORMAL





LIEBHERR LH30M 1253-123497


Component Rear Right Wheel Hub

GEAR OIL SAE 80W90 (C	GAL)				.,		
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		LH0272909	LH0212314	
	Sample Date		Client Info		11 Jan 2024	30 Dec 2021	
	Machine Age	hrs	Client Info		4554	981	
	Oil Age	hrs	Client Info		0	0	
	Filter Age	hrs	Client Info		0	0	
	Oil Changed		Client Info		Changed	Changed	
	Filter Changed		Client Info		N/A	None	
	Sample Status				NORMAL	NORMAL	
WEAR	Iron	ppm	ASTM D5185m	>450	8	10	
All component wear rates are normal.	Chromium	ppm	ASTM D5185m	>4	<1	<1	
	Nickel	ppm	ASTM D5185m		0	0	
	Titanium	ppm	ASTM D5185m		0	0	
	Silver	ppm	ASTM D5185m		0	<1	
	Aluminum	ppm	ASTM D5185m	>15	2	0	
	Lead	ppm	ASTM D5185m	>4	0	0	
	Copper	ppm	ASTM D5185m	>75	<1	2	
	Tin	ppm	ASTM D5185m		0	<1	
	Vanadium	ppm	ASTM D5185m		0	0	
	White Metal	scalar	*Visual	NONE	NONE	LIGHT	
	Yellow Metal	scalar	*Visual	NONE	NONE	NONE	
CONTAMINATION	Silicon	ppm	ASTM D5185m	>60	<1	3	
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m		<1	0	
	Water		WC Method	>0.2	NEG	NEG	
	Silt	scalar	*Visual	NONE	NONE	NONE	
	Debris	scalar	*Visual	NONE	NONE	NONE	
	Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	
	Appearance	scalar	*Visual	NORML	NORML	NORML	
	Odor	scalar	*Visual	NORML	NORML	NORML	
<u></u>	Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	
FLUID CONDITION	Sodium	ppm	ASTM D5185m		0	2	
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m	400	3	78	
	Barium	ppm	ASTM D5185m		3	0	
	Molybdenum	ppm	ASTM D5185m	12	0	<1	
	Manganese	ppm	ASTM D5185m		0	<1	
	Magnesium	ppm	ASTM D5185m		<1	1	
	Calcium	ppm	ASTM D5185m	150	53	274	
	Phosphorus	ppm	ASTM D5185m		347	464	
	Zinc	ppm	ASTM D5185m		0	149	
	Sulfur	ppm	ASTM D5185m		18332	21071	
	Visc @ 40°C	cSt	ASTM D445	143	119	113	













Laboratory Sample No. Lab Number

: LH0272909 : 06063175 Unique Number : 10834557 Test Package : CONST

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Recieved : 17 Jan 2024 Diagnosed : 19 Jan 2024 Diagnostician : Don Baldridge

SPARTAN RECYCLING

3071 HOWARD ST SPARTANBURG, SC US 29303

Contact: SERVICE MANAGER

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T:

F: