WEAR CONTAMINATION FLUID CONDITION

NORMAL NORMAL NORMAL

Area [634785]

VOLVO A40G 752073

Component Transmission (Auto)

			102 (· · · · · · · · · · · · · · · · · · ·			
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		VCP432200		
	Sample Date		Client Info		30 Nov 2023		
	Machine Age	hrs	Client Info		527		
	Oil Age	hrs	Client Info		527		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Not Changd		
	Filter Changed		Client Info		Not Changd		
	Sample Status				NORMAL		
VEAR	Iron	ppm	ASTM D5185m	>160	18		
All component wear rates are normal.	Chromium	ppm	ASTM D5185m	>5	<1		
	Nickel	ppm	ASTM D5185m	>5	<1		
	Titanium	ppm	ASTM D5185m		0		
	Silver	ppm	ASTM D5185m	>5	0		
	Aluminum	ppm	ASTM D5185m	>50	5		
	Lead	ppm	ASTM D5185m	>50	0		
	Copper	ppm	ASTM D5185m	>225	16		
	Tin	ppm	ASTM D5185m	>10	1		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	>20	10		
There is no indication of any contamination in the fluid.	Potassium	ppm	ASTM D5185m		2		
	Water	1-1-	WC Method		NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.1	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m		0		
The condition of the fluid is acceptable for the time in service.	Boron	ppm	ASTM D5185m	187	93		
The condition of the fluid is acceptable for the time in service.	Barium	ppm	ASTM D5185m		3		
	Molybdenum	ppm	ASTM D5185m	0.0	0		
	Manganese	ppm	ASTM D5185m		2		
	Magnesium	ppm	ASTM D5185m	6.8	0		
	Calcium	ppm	ASTM D5185m	215	74		
	Phosphorus	ppm	ASTM D5185m	445	250		
	Zinc	ppm	ASTM D5185m	56	0		
	Sulfur	ppm	ASTM D5185m	1336	2190		
	Visc @ 40°C	cSt	ASTM D445	35.3	28.8		





Certificate L2367

Laboratory Sample No. Lab Number **Unique Number**

: VCP432200 : 06063231 : 10834613 Test Package : MOB 1

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Recieved : 17 Jan 2024 Diagnosed : 19 Jan 2024 Diagnostician : Don Baldridge

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

RIPA AND ASSOCIATES

10149 FISHER AVENUE TAMPA, FL

US 33619 Contact: ROBERT TURNER

rturner@ripatampa.com

T: F: