

## [05W44323]

## JOHN DEERE 850L 1T0850LXVPF446530

## **Right Inner Final Drive**

## JOHN DEERE HY-GARD HYD/TRANS (--- GAL)

JOHN DEERE HT-GARD HTD/TRANS ( 0	<b>AL</b> )						
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		JR0199095	JR0183995	
	Sample Date		Client Info		15 Jan 2024	28 Aug 2023	
	Machine Age	hrs	Client Info		983	474	
	Oil Age	hrs	Client Info		983	0	
	Filter Age	hrs	Client Info		0	0	
	Oil Changed		Client Info		Changed	Not Changd	
	Filter Changed		Client Info		N/A	N/A	
	Sample Status				NORMAL	NORMAL	
WEAR	PQ		ASTM D8184	>1250	68	30	
All component wear rates are normal.	Iron	ppm	ASTM D5185m	>750	139	80	
	Chromium	ppm	ASTM D5185m	>9	1	<1	
	Nickel	ppm	ASTM D5185m	>10	<1	0	
	Titanium	ppm	ASTM D5185m		0	0	
	Silver	ppm	ASTM D5185m		0	0	
	Aluminum	ppm	ASTM D5185m	>40	<1	2	
	Lead	ppm	ASTM D5185m	>15	0	0	
	Copper	ppm	ASTM D5185m	>40	<1	0	
	Tin	ppm	ASTM D5185m	>10	0	<1	
	Vanadium	ppm	ASTM D5185m		0	0	
	White Metal	scalar	*Visual	NONE	NONE	NONE	
	Yellow Metal	scalar	*Visual	NONE	NONE	NONE	
CONTAMINATION There is no indication of any contamination in the oil.	Silicon	ppm	ASTM D5185m		4	5	
	Potassium	ppm	ASTM D5185m		<1	<1	
	Water		WC Method	>0.075	NEG	NEG	
	Silt	scalar	*Visual	NONE	NONE	NONE	
	Debris	scalar	*Visual	NONE	NONE	NONE	
	Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	
	Appearance	scalar	*Visual	NORML	NORML	NORML	
	Odor	scalar	*Visual	NORML	NORML	NORML	
	Emulsified Water	scalar	*Visual	>0.075	NEG	NEG	
FLUID CONDITION	Sodium	ppm	ASTM D5185m	>51	2	2	
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m	6	<1	<1	
	Barium	ppm	ASTM D5185m	0	0	0	
	Molybdenum	ppm	ASTM D5185m	0	<1	<1	
	Manganese	ppm	ASTM D5185m		1	1	
	Magnesium	ppm	ASTM D5185m	145	100	99	
	Calcium	ppm	ASTM D5185m		3427	3541	
	Phosphorus	ppm	ASTM D5185m		1028	1045	
	Zinc	ppm	ASTM D5185m		1200	1241	
	Sulfur	ppm	ASTM D5185m		3720	4315	

Visc @ 40°C


cSt

ASTM D445 57.0

Submitted By: TECHNICIAN ACCOUNT

53.3

52.0



**B & S SITE DEVLEOPMENT** Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513 Sample No. : JR0199095 Recieved : 17 Jan 2024 7800 PINEY BRANCH LANE Lab Number : 06063825 Diagnosed : 19 Jan 2024 BRISTOW, VA : 10835207 Unique Number Diagnostician : Wes Davis US 20136 Test Package : CONST (Additional Tests: PQ) Contact: DANNY HUFF Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369. dhuff@bandssite.com \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (540)270-3203 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (703)753-0605

Submitted By: TECHNICIAN ACCOUNT

Page 2 of 2