
**WEAR CONTAMINATION FLUID CONDITION** 

**NORMAL ABNORMAL NORMAL** 

## TRANE 102677 (S/N 1104F06031)

Component Refrigeration Compressor

RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
No corrective action is recommended at this time. Resample at the next service interval to monitor.	Sample Number		Client Info		WC0812240		
	Sample Date		Client Info		27 Dec 2023		
	Machine Age	hrs	Client Info		0		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		N/A		
	Filter Changed		Client Info		N/A		
	Sample Status				ABNORMAL		
WEAD			AOTA DEADE				
WEAR	Iron	ppm	ASTM D5185m		<1		
All component wear rates are normal.	Chromium	ppm	ASTM D5185m	>2	0		
	Nickel	ppm	ASTM D5185m		0		
	Titanium	ppm	ASTM D5185m	0	0		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m		0		
	Lead	ppm	ASTM D5185m		0		
	Copper	ppm	ASTM D5185m		<1		
	Tin	ppm	ASTM D5185m	>4	<1		
	Vanadium	ppm	ASTM D5185m	NONE	<1 NONE		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	>15	<b>△</b> 50		
Elemental level of silicon (Si) above normal.	Potassium	ppm	ASTM D5185m	>20	0		
	Water	%	ASTM D6304	>0.01	0.014		
	ppm Water	ppm	ASTM D6304	>100	146		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	LIGHT		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	<b>Emulsified Water</b>	scalar	*Visual	>0.01	NEG		
FLUID CONDITION	C = 41:		ACTM DE10E		•		
-LOID CONDITION	Sodium	ppm	ASTM D5185m		0		
The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.	Boron Barium	ppm	ASTM D5185m ASTM D5185m		0		
		ppm			0		
	Molybdenum	ppm	ASTM D5185m		0		
	Manganese	ppm	ASTM D5185m		0		
	Magnesium Calcium	ppm	ASTM D5185m ASTM D5185m		0		
		ppm					
	Phosphorus	ppm	ASTM D5185m		36 0		
	Zino	0000					
	Zinc	ppm	ASTM D5185m				
	Zinc Sulfur Acid Number (AN)	ppm ppm mg KOH/g	ASTM D5185m		3 0.042		







Certificate L2367

Laboratory Sample No. Lab Number **Unique Number** 

: 06065712 : 10837094 Test Package : IND 2

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : WC0812240 Recieved : 19 Jan 2024 Diagnosed : 23 Jan 2024

Diagnostician : Angela Borella

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

**DAIKIN APPLIED-RICHMOND** 

3524 MAYLAND CT RICHMOND, VA US 23233

Contact: GANIS HEISLER ganis.heisler@daikin.com T: (804)747-4822

F: (804)747-6686