

#### Machine Id CR6626 Component Rear Left Gearbox Fluid GEAR OIL ISO 220 (--- GAL)

# RECOMMENDATION

Resample at the next service interval to monitor.

#### WEAR

All component wear rates are normal.

### CONTAMINATION

There is no indication of any contamination in the oil.

-----

## FLUID CONDITION

The condition of the oil is acceptable for the time in service.

TestUOMMethodLimit/AbnCurrentHistory1HisSample NumberClient InfoMC0809525Sample DateClient Info25 Jan 2024	tory2
Sample Date         Client Info         25 Jan 2024	
Machine Age hrs Client Info 11006	
Oil Age hrs Client Info 0	
Filter Age hrs Client Info 0	
Oil Changed Client Info Changed	
Filter Changed Client Info Changed	
Sample Status NORMAL	
Iron ppm ASTM D5185m >200 <b>54</b>	
Aluminum         ppm         ASTM D5185m         >25         2          -	
Tin         ppm         ASTM D5185m         >10         <1	
Vanadium ppm ASTM D5185m 0	
White Metal scalar *Visual NONE NONE	
Yellow Metal scalar *Visual NONE NONE	
Silicon ppm ASTM D5185m >50 4	
Odor scalar *Visual NORML NORML	
Emulsified Water scalar *Visual >0.2 NEG	
Sodium         ppm         ASTM D5185m         0          -	
Boron         ppm         ASTM D5185m         50         2	
Barium         ppm         ASTM D5185m         15         0	
Molybdenum         ppm         ASTM D5185m         15         <1	
Manganese ppm ASTM D5185m <1	
Magnesium         ppm         ASTM D5185m         50         <1	
Calcium ppm ASTM D5185m 50 3	
Phosphorus         ppm         ASTM D5185m         350         335	
Zinc ppm ASTM D5185m 100 <1	
Sulfur ppm ASTM D5185m 12500 4964	
Visc @ 40°C cSt ASTM D445 220 202	

Contact/Location: MICHAEL LAWSON - BUCGRA



Ferrous Alloys 55 50 nickel 45 40 35 30 2! 20 15 10 0 Non-ferrous Metals 10 lead mdo Viscosity @ 40°C 24 240 235 230 22! C20 (40°C) 21 210 205 200 Abnorma 195 Jan 25/24 an 25

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 **BUCKNER HEAVY LIFT** Laboratory Sample No. : WC0809525 Recieved : 30 Jan 2024 4732 NC 54 EAST Lab Number : 06074195 : 31 Jan 2024 GRAHAM, NC Diagnosed Unique Number : 10856286 Diagnostician : Sean Felton US 27253-9215 Test Package : CONST Contact: MICHAEL LAWSON To discuss this sample report, contact Customer Service at 1-800-237-1369. michaell@bucknercompanies.com \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (336)376-8888 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (336)376-4090

Report Id: BUCGRA [WUSCAR] 06074195 (Generated: 01/31/2024 15:02:23) Rev: 1

Certificate L2367

Contact/Location: MICHAEL LAWSON - BUCGRA

Page 2 of 2