

**WEAR** CONTAMINATION **FLUID CONDITION** 


**NORMAL NORMAL ATTENTION** 



## **JOHN DEERE 544G 1YN544GAPPLA00193**

Component Rear Differential

JOHN DEERE GL-5 80W90 (	GAL)						
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		JR0197590		
	Sample Date		Client Info		28 Jan 2024		
	Machine Age	hrs	Client Info		544		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Not Changd		
	Filter Changed		Client Info		N/A		
	Sample Status				ATTENTION		
WEAR	PQ		ASTM D8184		58		
All component wear rates are normal.	Iron	ppm	ASTM D5185m	>500	137		
	Chromium	ppm	ASTM D5185m	>10	<1		
	Nickel	ppm	ASTM D5185m	>10	<1		
	Titanium	ppm	ASTM D5185m		<1		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m	>25	2		
	Lead	ppm	ASTM D5185m	>25	2		
	Copper	ppm	ASTM D5185m	>100	14		
	Tin	ppm	ASTM D5185m	>10	0		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION  There is no indication of any contamination in the oil.	Silicon	ppm	ASTM D5185m	>75	15		
	Potassium	ppm	ASTM D5185m	>20	2		
	Water		WC Method	>.2	NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>.2	NEG		
FLUID CONDITION  The oil viscosity is lower than normal. This plus the additive levels indicates the addition of a different brand, or type of oil. Confirm oil type.	Sodium	ppm	ASTM D5185m		0		
	Boron	ppm	ASTM D5185m		<b>3</b>		
	Barium	ppm	ASTM D5185m		1		
	Molybdenum	ppm	ASTM D5185m		<1		
	Manganese	ppm	ASTM D5185m		2		
	Magnesium	ppm	ASTM D5185m		<b>103</b>		
	Calcium	ppm	ASTM D5185m		▲ 3424		
	Phosphorus	ppm	ASTM D5185m		▲ 1079 ▲ 4070		
	Zinc	ppm	ASTM D5185m		▲ 1272 ▲ 4070		
	Sulfur	ppm	ASTM D5185m		▲ 4276 ▲ 52.5		
	Visc @ 40°C	cSt	ASTM D445	'	53.5		





Certificate L2367

Laboratory Sample No. Lab Number **Unique Number** 

: JR0197590 : 06075070 : 10857161 Test Package : CONST ( Additional Tests: PQ )

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Recieved Diagnosed

: 30 Jan 2024 : 01 Feb 2024 Diagnostician : Don Baldridge

JRE - GARNER 4161 AUBURN CHURCH RD GARNER, NC

US 27529 Contact: RALEIGH SHOP

sean.betts@jamesriverequipment.com;catherine.anastasio@wearcheck.com

To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T: (919)614-2260 F: (919)779-5432