WEAR CONTAMINATION FLUID CONDITION


NORMAL NORMAL NORMAL

[W8430]

JOHN DEERE 700L 1T0700LXEPF449590

Component Transmission (Manual)

JOHN DEERE HY-GARD HYD/TRANS (27 GAI	<u>-)</u>						
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor. (Customer Sample Comment: W8430)	Sample Number		Client Info		JR0183123		
	Sample Date		Client Info		25 Jan 2024		
	Machine Age	hrs	Client Info		528		
	Oil Age	hrs	Client Info		528		
	Filter Age	hrs	Client Info		528		
	Oil Changed		Client Info		Not Changd		
	Filter Changed		Client Info		Not Changd		
	Sample Status				NORMAL		
WEAR	PQ		ASTM D8184	>95	17		
All component wear rates are normal.	Iron	ppm	ASTM D5185m	>200	7		
	Chromium	ppm	ASTM D5185m	>5	<1		
	Nickel	ppm	ASTM D5185m	>5	0		
	Titanium	ppm	ASTM D5185m		<1		
	Silver	ppm	ASTM D5185m	>7	0		
	Aluminum	ppm	ASTM D5185m	>25	<1		
	Lead	ppm	ASTM D5185m		0		
	Copper	ppm	ASTM D5185m		3		
	Tin	ppm	ASTM D5185m	>10	<1		
	Vanadium	ppm	ASTM D5185m		<1		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION There is no indication of any contamination in the fluid.	Silicon	ppm	ASTM D5185m	>125	2		
	Potassium	ppm	ASTM D5185m	>20	2		
	Water		WC Method	>0.1	NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.1	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m		<1		
The condition of the fluid is acceptable for the time in service.	Boron	ppm	ASTM D5185m	6	0		
	Barium	ppm	ASTM D5185m	0	0		
	Molybdenum	ppm	ASTM D5185m	0	<1		
	Manganese	ppm	ASTM D5185m		<1		
	Magnesium	ppm	ASTM D5185m		<1		
	Calcium	ppm	ASTM D5185m		80		
	Phosphorus	ppm	ASTM D5185m		664		
	Zinc	ppm	ASTM D5185m	1640	827		
	Sulfur	ppm	ASTM D5185m		1613		
	Visc @ 40°C	cSt	ASTM D445	57.0	59.1		





Certificate L2367

Laboratory Sample No. Lab Number **Unique Number**

: JR0183123 : 06075620 : 10857711

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : 31 Jan 2024 Recieved Diagnosed : 02 Feb 2024

Diagnostician : Jonathan Hester

Test Package : MOBCE (Additional Tests: PQ, PrtCount) To discuss this sample report, contact Customer Service at 1-800-237-1369.

Contact: RALEIGH SHOP sean.betts@jamesriverequipment.com;catherine.anastasio@wearcheck.com T: (919)614-2260

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: (919)779-5432

4161 AUBURN CHURCH RD

JRE - GARNER

GARNER, NC

US 27529