


WEAR CONTAMINATION **FLUID CONDITION**

ABNORMAL NORMAL **NORMAL**

Machine Id

176 Component

Transmission							
{not provided} (GAL)							
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
No corrective action is recommended at this time. Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.	Sample Number		Client Info		WC06084015		
	Sample Date		Client Info		07 Feb 2024		
	Machine Age	mls	Client Info		427212		
	Oil Age	mls	Client Info		0		
	Filter Age	mls	Client Info		0		
	Oil Changed		Client Info		N/A		
	Filter Changed		Client Info		N/A		
	Sample Status				ABNORMAL		
WEAR	Iron	ppm	ASTM D5185m	>200	204		
The iron level is abnormal. All other component wear rates are normal.	Chromium	ppm	ASTM D5185m		2		
	Nickel	ppm	ASTM D5185m		0		
	Titanium	ppm	ASTM D5185m		<1		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m	>50	4		
	Lead	ppm	ASTM D5185m	>50	0		
	Copper	ppm	ASTM D5185m	>200	29		
	Tin	ppm	ASTM D5185m	>10	<1		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	>50	2		
There is no indication of any contamination in the fluid.	Potassium	ppm	ASTM D5185m	>20	13		
	Water		WC Method	>0.1	NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	LIGHT		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.1	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m		9		
The condition of the fluid is acceptable for the time in service.	Boron	ppm	ASTM D5185m		259		
	Barium	ppm	ASTM D5185m		10		
	Molybdenum	ppm	ASTM D5185m		0		
	Manganese	ppm	ASTM D5185m		34		
	Magnesium	ppm	ASTM D5185m		4		
	Calcium	ppm	ASTM D5185m		59		
	Phosphorus	ppm	ASTM D5185m		1023		
	Zinc	ppm	ASTM D5185m		62		
	Sulfur	ppm	ASTM D5185m		989		
	Visc @ 40°C	cSt	ASTM D445		113		







Certificate L2367

Laboratory Sample No. Unique Number : 10871460

Lab Number : 06084015

: WC06084015

Received Tested Diagnosed

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : 08 Feb 2024

: 11 Feb 2024

: 11 Feb 2024 - Don Baldridge

LONNIE SONGER 1820 SHELTON MISSION RD GREENEVILLE, TN

US 37743

Contact: LONNIE SONGER

Test Package : FLEET (Additional Tests: Glycol) To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T:

F: