WEAR CONTAMINATION **FLUID CONDITION** **NORMAL NORMAL NORMAL**

Machine Id

MOFFETT 1346

Component Diesel Engine

ECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History
Resample at the next service interval to monitor.	Sample Number		Client Info		WC0893853		
	Sample Date		Client Info		25 Jan 2024		
	Machine Age	hrs	Client Info		2685		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Changed		
	Filter Changed		Client Info		Changed		
	Sample Status				NORMAL		
EAR	Iron	ppm	ASTM D5185m	>100	3		
	Chromium	ppm	ASTM D5185m		<1		
All component wear rates are normal.	Nickel	ppm	ASTM D5185m		0		
	Titanium	ppm	ASTM D5185m		0		
	Silver	ppm	ASTM D5185m	>3	0		
	Aluminum	ppm	ASTM D5185m		1		
	Lead	ppm	ASTM D5185m		0		
	Copper	ppm	ASTM D5185m		0		
	Tin	ppm	ASTM D5185m		0		
	Vanadium	ppm	ASTM D5185m	_	0		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
ONTAMINATION	Silicon	nnm	ASTM D5185m	. 25	ο		
JNT AMINATION		ppm			9		
There is no indication of any contamination in the oil.	Potassium Fuel	ppm	ASTM D5185m		-		
			WC Method		<1.0 NEG		
	Water Glycol		WC Method	>0.2	NEG		
	Soot %	%	*ASTM D7844	. 2	0.1		
	Nitration	Abs/cm	*ASTM D7624	>20	4.5		
	Sulfation	Abs/.1mm	*ASTM D7024		17.1		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt		*Visual		NONE		
		scalar	*Visual	NONE NORML	NORML		
	Appearance Odor	scalar scalar	*Visual	NORML	NORML		
	Emulsified Water		*Visual	>0.2	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m		<1		
The BN result indicates that there is suitable alkalinity remaining in the	Boron	ppm	ASTM D5185m		9		
oil. The condition of the oil is suitable for further service.	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m	100	58		
	Manganese	ppm	ASTM D5185m	450	<1		
	Magnesium	ppm	ASTM D5185m		918		
	Calcium	ppm	ASTM D5185m		1050		
	Phosphorus	ppm	ASTM D5185m		1069		
	Zinc	ppm	ASTM D5185m		1217		
	Sulfur	ppm	ASTM D5185m		3039		
	Oxidation	Abs/.1mm	*ASTM D7414		12.8		
	Base Number (BN)	mg KOH/g	ASTM D2896	8.5	9.4		







Laboratory Sample No.

: WC0893853 Lab Number : 06085860 Unique Number : 10873305

Test Package : MOB 1 (Additional Tests: TBN)

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 12 Feb 2024

Tested : 13 Feb 2024 Diagnosed

: 13 Feb 2024 - Wes Davis

CONCRETE SERVICE CO - FAY BLOCK

161 BUILDERS BLVD FAYETTEVILLE, NC US 28301

Contact: Service Manager

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T:

F: