

#### Machine Id **12365** Component **Differential** Fluid **GEAR OIL SAE 75W90 (--- QTS)**

# RECOMMENDATION

Oil and filter change at the time of sampling has been noted. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition.

### WEAR

The iron level is severe. Gear wear is indicated.

## CONTAMINATION

There is no indication of any contamination in the oil.


------


# FLUID CONDITION

The oil is no longer serviceable as a result of the abnormal and/or severe wear.

Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		WC0882680		
Sample Date		Client Info		10 Feb 2024		
Machine Age	mls	Client Info		59559		
Oil Age	mls	Client Info		0		
Filter Age	mls	Client Info		0		
Oil Changed		Client Info		Changed		
Filter Changed		Client Info		Changed		
Sample Status				SEVERE		
Iron	ppm	ASTM D5185m	>500	3432		
Chromium	ppm	ASTM D5185m	>10	8		
Nickel	ppm	ASTM D5185m	>10	6		
Titanium	ppm	ASTM D5185m		2		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>25	3		
Lead	ppm	ASTM D5185m	>25	0		
Copper	ppm	ASTM D5185m	>100	55		
Tin	ppm	ASTM D5185m	>10	<1		
Vanadium	ppm	ASTM D5185m		1		
White Metal	scalar	*Visual	NONE	NONE		
Yellow Metal	scalar	*Visual	NONE	NONE		
Silicon	ppm	ASTM D5185m	>75	19		
Potassium	ppm	ASTM D5185m	>20	2		
Water		WC Method	>.2	NEG		
Silt	scalar	*Visual	NONE	NONE		
Debris	scalar	*Visual	NONE	NONE		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	NORML		
Odor	scalar	*Visual	NORML	NORML		
Emulsified Water	scalar	*Visual	>.2	NEG		
Sodium	ppm	ASTM D5185m		58		
Boron	ppm	ASTM D5185m	400	67		
Barium	ppm	ASTM D5185m	200	0		
Molybdenum	ppm	ASTM D5185m	12	<1		
Manganese	ppm	ASTM D5185m	10	82		
Magnesium	ppm	ASTM D5185m	12	3		
Calcium	ppm	ASTM D5185m	150	8		
Phosphorus	ppm	ASTM D5185m	1650	1023		
Zinc	ppm	ASTM D5185m	125	64		
Sulfur	ppm	ASTM D5185m ASTM D445	22500 109	20986 79.2		
Visc @ 40°C	cSt					

Contact/Location: SCOTT SULLIVAN - MSCDUR





SULLIVAN EASTERN INC : WearCheck USA - 501 Madison Ave., Cary, NC 27513 : WC0882680 Received 2860 C SLATER RD : 13 Feb 2024 Lab Number : 06088424 : 14 Feb 2024 MORRISVILLE, NC Tested Unique Number : 10875869 : 15 Feb 2024 - Sean Felton US 27560 Diagnosed Test Package : CONST Contact: SCOTT SULLIVAN To discuss this sample report, contact Customer Service at 1-800-237-1369. ssullivan@sullivaneastern.com \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (919)484-8993 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (919)484-2136



Certificate L2367

Laboratory

Sample No.

Contact/Location: SCOTT SULLIVAN - MSCDUR

Page 2 of 2