
**WEAR** CONTAMINATION **FLUID CONDITION** 

**NORMAL NORMAL NORMAL** 

## **NOT GIVEN IL0034834**

Component Diesel Engine

ECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History
Resample at the next service interval to monitor.	Sample Number		Client Info		IL0034834		
	Sample Date		Client Info		22 Feb 2024		
	Machine Age	mls	Client Info		0		
	Oil Age	mls	Client Info		0		
	Filter Age	mls	Client Info		0		
	Oil Changed		Client Info		N/A		
	Filter Changed		Client Info		N/A		
	Sample Status				NORMAL		
/EAR	Iron	ppm	ASTM D5185m	>100	38		
	Chromium	ppm	ASTM D5185m		1		
All component wear rates are normal.	Nickel	ppm	ASTM D5185m		<1		
	Titanium	ppm	ASTM D5185m		0		
	Silver	ppm	ASTM D5185m	>3	0		
	Aluminum	ppm	ASTM D5185m		14		
	Lead	ppm	ASTM D5185m		0		
	Copper	ppm	ASTM D5185m		3		
	Tin	ppm	ASTM D5185m		<1		
	Vanadium	ppm	ASTM D5185m	7.0	0		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
ONTANUNATION							
ONTAMINATION	Silicon	ppm	ASTM D5185m		8		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m		24		
	Fuel	%	ASTM D3524		<1.0		
	Water		WC Method	>0.2	NEG		
	Glycol	0/	WC Method	0	NEG		
	Soot %	%	*ASTM D7844		0.8		
	Nitration	Abs/cm	*ASTM D7624		10.2		
	Sulfation	Abs/.1mm	*ASTM D7415		22.1		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.2	NEG		
LUID CONDITION	Sodium	ppm	ASTM D5185m		4		
	Boron	ppm	ASTM D5185m		41		
The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m		41		
	Manganese	ppm	ASTM D5185m		<1		
	Magnesium	ppm	ASTM D5185m		496		
	Calcium	ppm	ASTM D5185m		1573		
	Phosphorus	ppm	ASTM D5185m		732		
	Zinc	ppm	ASTM D5185m		875		
	Sulfur	ppm	ASTM D5185m		2277		
	Oxidation	Abs/.1mm	*ASTM D7414	>25	21.3		
	Base Number (BN)		ASTM D2896		9.1		
	Visc @ 100°C	cSt	ASTM D445		10.7		







Laboratory Sample No.

Lab Number : 06098090 Unique Number: 10896320

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : IL0034834 Received : 23 Feb 2024 **Tested** : 26 Feb 2024

Diagnosed : 26 Feb 2024 - Sean Felton Test Package : FLEET ( Additional Tests: FuelDilution )

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

**IDEALEASE OF ATLANTA - FULTON** 

4675 BAKERS FERRY ROAD ATLANTA, GA

US 30331 Contact: DAVID JOHNS

davidjohns@idealease.com T: (404)699-5571

F: (404)699-7420

Contact/Location: DAVID JOHNS - IDEATLGA