**WEAR** CONTAMINATION **FLUID CONDITION** 


**NORMAL ABNORMAL NORMAL** 

Machine Id

195-1088

Component
Hydraulic System

RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
	Sample Number		Client Info		JR0185842	JR0202578	JR0181084
We recommend you service the filters on this component. Resample at the next service interval to monitor.	Sample Date		Client Info		22 Feb 2024	15 Feb 2024	10 Aug 202
	Machine Age	hrs	Client Info		1191	1181	943
	Oil Age	hrs	Client Info		1191	1181	943
	Filter Age	hrs	Client Info		0	0	0
	Oil Changed		Client Info		Not Changd	Not Changd	Not Change
	Filter Changed Sample Status		Client Info		Not Changd ABNORMAL	Not Changd SEVERE	Changed NORMAL
VEAR	PQ		ASTM D8184		14	20	14
<u> </u>	Iron	ppm	ASTM D5185m	>20	3	2	4
All component wear rates are normal.	Chromium	ppm	ASTM D5185m	>10	0	0	0
	Nickel	ppm	ASTM D5185m	>10	<1	<1	0
	Titanium	ppm	ASTM D5185m		0	0	0
	Silver	ppm	ASTM D5185m		0	0	0
	Aluminum	ppm	ASTM D5185m		<1	<1	<1
	Lead	ppm	ASTM D5185m		0	3	<1
	Copper	ppm	ASTM D5185m		2	9	2
	Tin	ppm	ASTM D5185m	>10	<1	<1	0
	Vanadium	ppm	ASTM D5185m	NONE	0	0	0
	White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
	Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
CONTAMINATION	Silicon	ppm	ASTM D5185m	>20	2	4	2
There is a high amount of neuticulates present in the ail	Potassium	ppm	ASTM D5185m	>20	<1	3	0
There is a high amount of particulates present in the oil.	Water		WC Method	>0.1	NEG	NEG	NEG
	Particles >4µm		ASTM D7647		<u> </u>		2391
	Particles >6µm		ASTM D7647		<u>▲</u> 3067		823
	Particles >14µm		ASTM D7647		▲ 203 ▲ 54		99
	Particles >21µm Particles >38µm		ASTM D7647 ASTM D7647		3		21
	Particles >30µm		ASTM D7647		0		0
	Oil Cleanliness		ISO 4406 (c)		<u>^</u> 21/19/15		18/17/14
	Silt	scalar	*Visual	NONE	NONE	NONE	NONE
	Debris	scalar	*Visual	NONE	NONE	NONE	NONE
	Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
	Appearance	scalar	*Visual	NORML	NORML	▲ MILKY	NORM
	Odor	scalar	*Visual	NORML	NORML	NORML	NORM
	Emulsified Water	scalar	*Visual	>0.1	NEG	<b>△</b> 0.2%	NEG
LUID CONDITION	Sodium	ppm	ASTM D5185m		2	2	0
The ANI level is accordable for this fluid. The condition of the eff	Boron	ppm	ASTM D5185m		3	1	2
The AN level is acceptable for this fluid. The condition of the oils additive package is suitable for further service.	Barium	ppm	ASTM D5185m		0	0	0
additive package is suitable for further service.	Molybdenum	ppm	ASTM D5185m		0	0	2
	Manganese	ppm	ASTM D5185m		<1	<1	0
	Magnesium	ppm	ASTM D5185m		16	17	16
	Calcium	ppm	ASTM D5185m		126	121	131
	Phosphorus	ppm	ASTM D5185m		565 705	589	573
	Zinc	ppm	ASTM D5185m		765	779	759
	Culfur	nnm	VCTVI DE10E~		1716	1715	1700
	Sulfur Acid Number (AN)	ppm mg KOH/g	ASTM D5185m ASTM D8045		1716 1.06	1715 0.67	1782 0.75





Laboratory Sample No.

Lab Number : 06098848 Unique Number : 10897078

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : JR0185842

Received Tested

: 23 Feb 2024 : 23 Feb 2024 : 23 Feb 2024 - Doug Bogart Diagnosed

4161 AUBURN CHURCH RD GARNER, NC

US 27529 Contact: RALEIGH SHOP

JRE - GARNER

Test Package : CONST ( Additional Tests: PQ ) To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

sean.betts@jamesriverequipment.com;catherine.anastasio@wearcheck.com T: (919)614-2260

Submitted By: CSA EASTERN NC

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: (919)779-5432