

## WEAR NORMAL CONTAMINATION NORMAL FLUID CONDITION ATTENTION



## TEREX AC80-2 7955 (S/N 48268)

3 Differential

GEAR OIL SAE 85W140 (--- GAL)

RECOMMENDATION

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor.



All component wear rates are normal.

## CONTAMINATION


There is no indication of any contamination in the oil.


## FLUID CONDITION

The oil viscosity is lower than normal. Confirm oil type.

_)						
Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		DC0031995		
Sample Date		Client Info		11 Dec 2023		
Machine Age	hrs	Client Info		1287		
Oil Age	hrs	Client Info		0		
Filter Age	hrs	Client Info		0		
Oil Changed		Client Info		Changed		
Filter Changed		Client Info		N/A		
Sample Status				ATTENTION		
Iron	ppm	ASTM D5185m	>500	44		
Chromium	ppm	ASTM D5185m	>10	<1		
Nickel	ppm	ASTM D5185m	>10	<1		
Titanium	ppm	ASTM D5185m		<1		
Silver	ppm	ASTM D5185m	0.5	<1		
Aluminum	ppm	ASTM D5185m	>25	<1		
Lead	ppm	ASTM D5185m	>25	<1		
Copper	ppm	ASTM D5185m	>100	12		
Tin	ppm	ASTM D5185m	>10	<1		
Vanadium	ppm	ASTM D5185m	NONE	0		
White Metal	scalar	*Visual	NONE	NONE		
Yellow Metal	scalar	*Visual	NONE	NONE		
Silicon	ppm	ASTM D5185m	>75	4		
Potassium	ppm	ASTM D5185m	>20	1		
Water		WC Method	>.2	NEG		
Silt	scalar	*Visual	NONE	NONE		
Debris	scalar	*Visual	NONE	NONE		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	NORML		
Odor	scalar	*Visual	NORML	NORML		
Emulsified Water	scalar	*Visual	>.2	NEG		
Sodium	ppm	ASTM D5185m		0		
Boron	ppm	ASTM D5185m	400	115		
Barium	ppm	ASTM D5185m	200	26		
Molybdenum	ppm	ASTM D5185m	12	1		
Manganese	ppm	ASTM D5185m	10	2		
Magnesium	ppm	ASTM D5185m	12	3		
Calcium	ppm	ASTM D5185m	150	24		
Phosphorus	ppm	ASTM D5185m	1650	809		
Zinc	ppm	ASTM D5185m	125	17		
Sulfur	ppm	ASTM D5185m	22500	28908		
Visc @ 40°C	cSt	ASTM D445	368	157	)	

Contact/Location: TONY DAVIS - CRAABEMD





ABERDEEN PROVING GROUND Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513 Sample No. Received 6721 RARITON AVENUE : DC0031995 : 23 Feb 2024 Lab Number : 06099481 ABERDEEN, MD Tested : 26 Feb 2024 Unique Number : 10897711 : 27 Feb 2024 - Don Baldridge US 21005 Diagnosed Test Package : MOB 1 Contact: TONY DAVIS Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369. tdavis@vacraneworks.com \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (410)688-1725 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F:

國

Contact/Location: TONY DAVIS - CRAABEMD