**WEAR** CONTAMINATION **FLUID CONDITION**  **NORMAL NORMAL NORMAL** 

## HITACHI E-6

Component Final Drive

RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number	OOM	Client Info	Little/ton	LP0001009		
	Sample Date		Client Info		23 Jan 2024		
	Machine Age	hrs	Client Info		12147		
	Oil Age	hrs	Client Info		1000		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Changed		
	Filter Changed		Client Info		Changed		
	Sample Status				NORMAL		
VEAR	Iron	ppm	ASTM D5185m	>500	175		
	Chromium	ppm	ASTM D5185m		2		
All component wear rates are normal.	Nickel	ppm	ASTM D5185m		0		
	Titanium	ppm	ASTM D5185m	- 10	0		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m	>25	<1		
	Lead	ppm	ASTM D5185m		0		
	Copper	ppm	ASTM D5185m		0		
	Tin	ppm	ASTM D5185m	>10	0		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	>75	4		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m		0		
	Water	1-1-	WC Method		NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.2	NEG		
LUID CONDITION	Sodium	ppm	ASTM D5185m		0		
The AN level is acceptable for this fluid. The condition of the oil is	Boron	ppm	ASTM D5185m		0		
suitable for further service.	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m		<1		
	Manganese	ppm	ASTM D5185m		2		
	Magnesium	ppm	ASTM D5185m		10		
	Calcium	ppm	ASTM D5185m		18		
	Phosphorus	ppm	ASTM D5185m		698		
	Zinc	ppm	ASTM D5185m		9		
	Sulfur	ppm	ASTM D5185m		22823		
	Acid Number (AN)	mg KOH/g	ASTM D8045		1.34		
	Visc @ 40°C	cSt	ASTM D445		142		





Certificate L2367

Report Id: SMLWES [WUSCAR] 06101089 (Generated: 02/28/2024 03:17:47) Rev: 1

Laboratory Sample No.

: LP0001009 Lab Number : 06101089 Unique Number: 10899319 Test Package : MOB 2

To discuss this sample report, contact Customer Service at 1-800-237-1369.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 26 Feb 2024 **Tested** : 27 Feb 2024

: 27 Feb 2024 - Doug Bogart Diagnosed

10 GROVE ST WEST ROXBURY, MA US 02132

Contact: MARK ERWIN merwin@smlorusso.com

S.M. LORUSSO & SONS

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Contact/Location: MARK ERWIN - SMLWES

T:

F: