WEAR CONTAMINATION FLUID CONDITION


SEVERE NORMAL NORMAL

Machine Id

## JOHN DEERE 331G 1T0331GKLPF449953

Right Final Drive

JOHN DEERE GL-5 80W90 ( GAL)							
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
The oil change at the time of sampling has been noted. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition.	Sample Number		Client Info		JR0204264		
	Sample Date		Client Info		22 Feb 2024		
	Machine Age	hrs	Client Info		514		
	Oil Age	hrs	Client Info		514		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Changed		
	Filter Changed		Client Info		N/A		
	Sample Status				SEVERE		
WEAR	PQ		ASTM D8184	>1250	88		
Gear wear is indicated.	Iron	ppm	ASTM D5185m	>750	<b>2061</b>		
	Chromium	ppm	ASTM D5185m	>9	▲ 36		
	Nickel	ppm	ASTM D5185m	>10	4		
	Titanium	ppm	ASTM D5185m		1		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m		12		
	Lead	ppm	ASTM D5185m	>15	0		
	Copper	ppm	ASTM D5185m		2		
	Tin	ppm	ASTM D5185m	>10	0		
	Vanadium	ppm	ASTM D5185m		<1		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	>75	26		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m	>20	18		
	Water		WC Method	>0.075	NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.075	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m	>51	11		
The oil is no longer serviceable as a result of the abnormal and/or severe wear.	Boron	ppm	ASTM D5185m		2		
	Barium	ppm	ASTM D5185m		88		
	Molybdenum	ppm	ASTM D5185m		1		
	Manganese	ppm	ASTM D5185m		18		
	Magnesium	ppm	ASTM D5185m		9		
	Calcium	ppm	ASTM D5185m		51		
	Phosphorus	ppm	ASTM D5185m		264		
	Zinc	ppm	ASTM D5185m		15		
	Sulfur	ppm	ASTM D5185m		15068		
	Visc @ 40°C	cSt	ASTM D445		134		





Report Id: CARCHAJR [WUSCAR] 06101932 (Generated: 02/29/2024 14:10:56) Rev: 1

Laboratory Sample No.

Lab Number : 06101932 Unique Number : 10900162

: JR0204264

To discuss this sample report, contact Customer Service at 1-800-237-1369.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received **Tested** 

Diagnosed Test Package : CONST ( Additional Tests: PQ )

: 27 Feb 2024 : 28 Feb 2024

: 29 Feb 2024 - Sean Felton

**CARLTON'S BACKHOE** 9550 STATESVILLE ROAD CHARLOTTE, NC US 28269 Contact: LEO

T: (704)547-0211

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: