
WEAR CONTAMINATION **FLUID CONDITION**


NORMAL NORMAL NORMAL


PIERCE LADDER 1


Component

Hydraulic System							
{not provided} (GAL)							
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
No corrective action is recommended at this time. Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.	Sample Number		Client Info		WC0890664		
	Sample Date		Client Info		18 Feb 2024		
	Machine Age	hrs	Client Info		3633		
	Oil Age	hrs	Client Info		3633		
	Filter Age	hrs	Client Info		3633		
	Oil Changed		Client Info		Not Changd		
	Filter Changed		Client Info		Not Changd		
	Sample Status				NORMAL		
WEAR	Iron	ppm	ASTM D5185m	>20	0		
All component wear rates are normal.	Chromium	ppm	ASTM D5185m		<1		
	Nickel	ppm	ASTM D5185m		<1		
	Titanium	ppm	ASTM D5185m		<1		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m	>10	1		
	Lead	ppm	ASTM D5185m	>10	<1		
	Copper	ppm	ASTM D5185m	>75	2		
	Tin	ppm	ASTM D5185m	>10	0		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	>20	23		
Elemental level of silicon (Si) above normal indicating ingress of seal material.	Potassium	ppm	ASTM D5185m		<1		
	Water		WC Method	>0.1	NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.1	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m		1		
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m		28		
	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m		13		
	Manganese	ppm	ASTM D5185m		<1		
	Magnesium	ppm	ASTM D5185m		124		
	Calcium	ppm	ASTM D5185m		949		
	Phosphorus	ppm	ASTM D5185m		507		
	Zinc	ppm	ASTM D5185m		622		
	Sulfur	ppm	ASTM D5185m		1611		











Certificate L2367

Laboratory

Sample No. Lab Number : 06104709 Unique Number : 10902939

: WC0890664 Test Package : FLEET

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 29 Feb 2024 **Tested**

: 01 Mar 2024 : 04 Mar 2024 - Don Baldridge Diagnosed

CONCORD FIRE RESCUE 100 WARREN C COLEMAN BLVD

CONCORD, NC US 28027

Contact: WILLIAM

WILLIAMJ@CONCORDNC.GOV T: (704)920-5522

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Contact/Location: WILLIAM ? - CONCONDC

F: