**WEAR** CONTAMINATION **FLUID CONDITION**  **ABNORMAL NORMAL NORMAL** 

## JOHN DEERE 4630 1N04630XJE0028599

Component Front Right Final Drive


RECOMMENDATION  No corrective action is recommended at this time. Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.	Test	UOM	Method	Limit/Abn	Current	History1	History2
	Sample Number		Client Info		JR0201524		
	Sample Date		Client Info		29 Feb 2024		
	Machine Age	hrs	Client Info		0		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		N/A		
	Filter Changed		Client Info		N/A		
	Sample Status				ABNORMAL		
VEAR	PQ		ASTM D8184	>1250	148		
The copper level is abnormal. All other component wear rates are normal.	Iron	ppm	ASTM D5185m		462		
	Chromium	ppm	ASTM D5185m		6		
	Nickel	ppm	ASTM D5185m		<1		
	Titanium	ppm	ASTM D5185m		0		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m	>40	1		
	Lead	ppm	ASTM D5185m	>15	<1		
	Copper	ppm	ASTM D5185m	>40	<b>104</b>		
	Tin	ppm	ASTM D5185m	>10	4		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	>75	6		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m	>20	5		
	Water		WC Method	>0.075	NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.075	NEG		
LUID CONDITION	Sodium	ppm	ASTM D5185m	>51	6		
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m		7		
	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m		0		
	Manganese	ppm	ASTM D5185m		5		
	Magnesium	ppm	ASTM D5185m		2		
	Calcium	ppm	ASTM D5185m		26		
	Phosphorus	ppm	ASTM D5185m		274		
	Zinc	ppm	ASTM D5185m		37		
	Sulfur	ppm	ASTM D5185m		18767		

Visc @ 40°C

cSt

ASTM D445

358





Laboratory Sample No.

Lab Number : 06106339 Unique Number: 10909836

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : JR0201524

Received Tested

: 01 Mar 2024 : 04 Mar 2024 Diagnosed

: 05 Mar 2024 - Sean Felton

JRE - WAKEFIELD 10489 GENERAL MAHONE HWY WAKEFIELD, VA

US 23888

T: (757)899-3232

Contact: BILL ACKER backer@jamesriverequipment.com

To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Test Package : CONST ( Additional Tests: PQ )

F: (757)899-6464

Contact/Location: BILL ACKER - JAMWAK