WEAR CONTAMINATION **FLUID CONDITION**


NORMAL NORMAL NORMAL



Machine Id **JOHN DEERE 700H 940783**

Right Final Drive

{not provided} (GAL)							
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. (Customer Sample Comment: Final drive, right side, overfilled with trans oil)	Sample Number		Client Info		JR0212436		
	Sample Date		Client Info		16 Apr 2024		
	Machine Age	hrs	Client Info		15344		
	Oil Age	hrs	Client Info		15344		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		N/A		
	Filter Changed		Client Info		N/A		
	Sample Status				NORMAL		
WEAR	PQ		ASTM D8184	>1250	32		
All component wear rates are normal.	Iron	ppm	ASTM D5185m	>750	106		
	Chromium	ppm	ASTM D5185m	>9	2		
	Nickel	ppm	ASTM D5185m	>10	2		
	Titanium	ppm	ASTM D5185m		<1		
	Silver	ppm	ASTM D5185m		<1		
	Aluminum	ppm	ASTM D5185m	>40	4		
	Lead	ppm	ASTM D5185m	>15	2		
	Copper	ppm	ASTM D5185m	>40	7		
	Tin	ppm	ASTM D5185m	>10	1		
	Vanadium	ppm	ASTM D5185m		<1		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	>75	18		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m	>20	3		
	Water		WC Method	>0.075	NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.075	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m	>51	<1		
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m		166		
	Barium	ppm	ASTM D5185m		<1		
	Molybdenum	ppm	ASTM D5185m		125		
	Manganese	ppm	ASTM D5185m		2		
	Magnesium	ppm	ASTM D5185m		425		
	Calcium	ppm	ASTM D5185m		2298		
	Phosphorus	ppm	ASTM D5185m		1047		
	Zinc	ppm	ASTM D5185m		1097		
	Sulfur	ppm	ASTM D5185m		3803		
	Visc @ 40°C	cSt	ASTM D445		67.2		
Report Id: RWMGAR [WUSCAR] 06152306 (Generated: 04/23/2024 04:19:05) Rev: 1					Submitt	ed By: RALE	EIGH SHOP







Laboratory Sample No.

Lab Number : 06152306 Unique Number: 10982384

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : JR0212436

Tested Diagnosed

Received : 17 Apr 2024 : 18 Apr 2024

: 22 Apr 2024 - Sean Felton

JRE - GARNER 4161 AUBURN CHURCH RD GARNER, NC

US 27529 Contact: RALEIGH SHOP

Test Package : CONST (Additional Tests: PQ) Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369. sean.betts@jamesriverequipment.com;catherine.anastasio@wearcheck.com

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (919)614-2260 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (919)779-5432