

## Machine Id MANITOU MRT2550 MH8036 Component

## Front Center Axle

{not provided} (--- GAL)

RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		HPL0005067		
	Sample Date		Client Info		16 Apr 2024		
	Machine Age	hrs	Client Info		1425		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		N/A		
	Filter Changed		Client Info		N/A		
	Sample Status				NORMAL		
WEAR	Iron	ppm	ASTM D5185m	>500	230		
All component wear rates are normal.	Chromium	ppm	ASTM D5185m		<1		
	Nickel	ppm	ASTM D5185m		1		
	Titanium	ppm	ASTM D5185m		<1		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m	>25	5		
	Lead	ppm	ASTM D5185m	>25	<1		
	Copper	ppm	ASTM D5185m	>50	4		
	Tin	ppm	ASTM D5185m	>10	<1		
	Vanadium	ppm	ASTM D5185m		<1		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION There is no indication of any contamination in the oil.	Silicon	ppm	ASTM D5185m	>75	33		
	Potassium	ppm	ASTM D5185m		61		
	Water	le le		>0.2	NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.2	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m		17		
	Boron	ppm	ASTM D5185m		3		
The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.	Barium	ppm	ASTM D5185m		2		
	Molybdenum	ppm	ASTM D5185m		12		
	Manganese	ppm	ASTM D5185m		1		
	Magnesium	ppm	ASTM D5185m		33		
	Calcium	ppm	ASTM D5185m		2704		
	Phosphorus	ppm	ASTM D5185m		1072		
	Zinc	ppm	ASTM D5185m		1123		

Sulfur

Visc @ 40°C

ppm ASTM D5185m

ASTM D445

Acid Number (AN) mg KOH/g ASTM D8045


cSt

Contact/Location: DAVE KOEHNE - STEBOL

27633

0.40

41.91



Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513 STEVENSON CRANE Sample No. 410 STEVENSON DR : HPL0005067 Received : 24 Apr 2024 Lab Number : 06159329 BOLINGBROOK, IL Tested : 30 Apr 2024 : 30 Apr 2024 - Jonathan Hester US 60440 Unique Number : 10994752 Diagnosed Test Package : MOB 2 (Additional Tests: FT-IR, KV100, TBN) Contact: DAVE KOEHNE Certificate L2367 davidk@stevensoncrane.com To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (630)972-9199 F: Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Contact/Location: DAVE KOEHNE - STEBOL Page 2 of 2