


WEAR CONTAMINATION **FLUID CONDITION** **ABNORMAL** NORMAL **ATTENTION**

[702821 ALTA RENTS] VOLVO L90H 626583

Transmission

VOLVO SUPER HYDRAULIC O	IL 46 (GA	L)					
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
No corrective action is recommended at this time. Resample at the next service interval to monitor.	Sample Number		Client Info		VCP454748		
	Sample Date		Client Info		23 Apr 2024		
	Machine Age	hrs	Client Info		1279		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Not Changd		
	Filter Changed		Client Info		Not Changd		
	Sample Status				ABNORMAL		
WEAR	Iron	ppm	ASTM D5185m	>100	149		
The iron level is abnormal. All other component wear rates are normal.	Chromium	ppm	ASTM D5185m	>20	<1		
	Nickel	ppm	ASTM D5185m	>10	0		
	Titanium	ppm	ASTM D5185m		0		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m	>30	<1		
	Lead	ppm	ASTM D5185m	>50	0		
	Copper	ppm	ASTM D5185m	>50	11		
	Tin	ppm	ASTM D5185m	>20	0		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	>50	11		
There is no indication of any contamination in the fluid.	Potassium	ppm	ASTM D5185m	>20	0		
	Water		WC Method	>0.2	NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.2	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m		5		
The fluid viscosity is lower than normal. Confirm oil type.	Boron	ppm	ASTM D5185m	14	63		
	Barium	ppm	ASTM D5185m	0.0	0		
	Molybdenum	ppm	ASTM D5185m	0.0	0		
	Manganese	ppm	ASTM D5185m	0.0	9		
	Magnesium	ppm	ASTM D5185m	2.6	0		
	Calcium	ppm	ASTM D5185m	49	68		
	Phosphorus	ppm	ASTM D5185m	354	168		
	Zinc	ppm	ASTM D5185m	419	36		
	Sulfur	ppm	ASTM D5185m	3719	1823		
	Visc @ 40°C	cSt	ASTM D445	46	28.14		





Laboratory Sample No.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : VCP454748 Lab Number : 06161378

Tested Unique Number : 10996801 Diagnosed

Received : 26 Apr 2024 : 02 May 2024

: 02 May 2024 - Don Baldridge

ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC 9601 BOGGY CREEK RD ORLANDO, FL US 32824

Contact: Robert LaPlante robert.laplante@altg.com T: (407)508-9736

Test Package : MOB 2 (Additional Tests: PrtCount) Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: (407)659-8720