
WEAR CONTAMINATION FLUID CONDITION **NORMAL NORMAL NORMAL**


[W02008268]


VOLVO ECR355 314451


Rear Left Final Drive

RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History
The oil change at the time of sampling has been noted. Resample at	Sample Number		Client Info		ML0001054		
the next service interval to monitor. (Customer Sample Comment: W02008268)	Sample Date		Client Info		02 May 2024		
	Machine Age	hrs	Client Info		2007		
	Oil Age	hrs	Client Info		500		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Changed		
	Filter Changed		Client Info		N/A		
	Sample Status				NORMAL		
VEAR	Iron	ppm	ASTM D5185m	>500	240		
All component wear rates are normal.	Chromium	ppm	ASTM D5185m	>10	6		
	Nickel	ppm	ASTM D5185m	>10	<1		
	Titanium	ppm	ASTM D5185m		<1		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m	>25	2		
	Lead	ppm	ASTM D5185m	>25	0		
	Copper	ppm	ASTM D5185m	>50	4		
	Tin	ppm	ASTM D5185m	>10	0		
	Vanadium	ppm	ASTM D5185m		<1		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	>75	9		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m	>20	2		
	Water		WC Method	>0.2	NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.2	NEG		
LUID CONDITION	Sodium	ppm	ASTM D5185m		2		
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m	111	0		
	Barium	ppm	ASTM D5185m	0.0	1		
	Molybdenum	ppm	ASTM D5185m	0.9	<1		
	Manganese	ppm	ASTM D5185m	0.0	4		
	Magnesium	ppm	ASTM D5185m	39	2		
	Calcium	ppm	ASTM D5185m	93	8		
			ASTM D5185m	920	379		
	Phosphorus	ppm	710 1111 20 100111				
	Phosphorus Zinc	ppm		104	13		
	•			104	13 17153 163		











Certificate L2367

Report Id: VOLVO0002 [WUSCAR] 06174373 (Generated: 05/13/2024 12:16:09) Rev: 1

Laboratory Sample No.

: ML0001054 Lab Number : 06174373 Unique Number : 11020426 Test Package : CONST

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 09 May 2024 **Tested** : 10 May 2024

Diagnosed : 13 May 2024 - Don Baldridge

MCCLUNG-LOGAN EQUIPMENT CO - MANASSAS 8450 QUARRY ROAD

MANASSAS, VA US 20110

Contact: DARRELL ANDES dandes@mcclung-logan.com

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Submitted By: DARRELL ANDES

F: (703)393-7844

T: