
WEAR CONTAMINATION **FLUID CONDITION** **NORMAL NORMAL NORMAL**

Machine Id

TOYOTA 64921-5E Component Gasoline Engine Fluid

ECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History
Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.	Sample Number		Client Info		FS0000341		
	Sample Date		Client Info		13 Jun 2024		
	Machine Age	mls	Client Info		0		
	Oil Age	mls	Client Info		0		
	Filter Age	mls	Client Info		0		
	Oil Changed		Client Info		N/A		
	Filter Changed		Client Info		N/A		
	Sample Status				NORMAL		
/EAR	Iron	ppm	ASTM D5185m	>150	7		
TEAT.	Chromium	ppm	ASTM D5185m		, <1		
All component wear rates are normal.	Nickel	ppm	ASTM D5185m		0		
	Titanium	ppm	ASTM D5185m	70	<1		
	Silver	ppm	ASTM D5185m	>2	0		
	Aluminum	ppm	ASTM D5185m		2		
	Lead	ppm	ASTM D5185m		<1		
	Copper	ppm	ASTM D5185m		<1		
	Tin	ppm	ASTM D5185m		<1		
	Vanadium	ppm	ASTM D5185m	710	0		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
ONTAMINATION	Silicon	ppm	ASTM D5185m		18		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m		2		
	Fuel	%	ASTM D3524		<1.0		
	Water		WC Method	>0.2	NEG		
	Glycol	21	WC Method		NEG		
	Soot %	%	*ASTM D7844	0.0	0		
	Nitration	Abs/cm	*ASTM D7624		9.5		
	Sulfation	Abs/.1mm	*ASTM D7415		22.6		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.2	NEG		
LUID CONDITION	Sodium	ppm	ASTM D5185m	>400	3		
	Boron	ppm	ASTM D5185m		22		
The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m		70		
	Manganese	ppm	ASTM D5185m		9		
	Magnesium	ppm	ASTM D5185m		650		
	Calcium	ppm	ASTM D5185m		841		
	Phosphorus	ppm	ASTM D5185m		572		
	Zinc	ppm	ASTM D5185m		720		
	Sulfur	ppm	ASTM D5185m		2583		
	Oxidation	Abs/.1mm	*ASTM D7414	>25	15.8		
	Base Number (BN)	mg KOH/g	ASTM D2896		3.9		
	Visc @ 100°C	cSt	ASTM D445		8.4		





Report Id: FORTHO [WUSCAR] 06209925 (Generated: 06/19/2024 20:39:29) Rev: 1

Laboratory Sample No.

: FS0000341 Lab Number : 06209925 Unique Number : 11082789

To discuss this sample report, contact Customer Service at 1-800-237-1369.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 14 Jun 2024 **Tested** : 19 Jun 2024 Diagnosed

: 19 Jun 2024 - Jonathan Hester Test Package: MOB 1 (Additional Tests: FuelDilution, PercentFuel, TBN)

FORENSIC & SCIENTIFIC TESTING 21 INDUSTRIAL DR THORSBY, AL US 35171

Contact: SHAREE WELLS swells@fast-lab.com T: (205)646-0071

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Contact/Location: SHAREE WELLS - FORTHO