

WEAR CONTAMINATION **FLUID CONDITION** **NORMAL NORMAL NORMAL**



Machine Id VOLVO ECR145 316780 Component Swing Drive

GEAR OIL SAE 85W140 (GA	L)						
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		VCP443017		
	Sample Date		Client Info		11 Jun 2024		
	Machine Age	hrs	Client Info		516		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Changed		
	Filter Changed		Client Info		Not Changd		
	Sample Status				NORMAL		
WEAR	Iron	ppm	ASTM D5185m	>1200	59		
	Chromium	ppm	ASTM D5185m		<1		
All component wear rates are normal.	Nickel	ppm	ASTM D5185m		<1		
	Titanium	ppm	ASTM D5185m	,	<1		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m	>25	1		
	Lead	ppm	ASTM D5185m		<1		
	Copper	ppm	ASTM D5185m	>50	28		
	Tin	ppm	ASTM D5185m	>10	<1		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	0.11.		AOTIA DELOE	400	40		
CONTAMINATION	Silicon	ppm	ASTM D5185m		18		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m		1		
	Water	cooler	WC Method *Visual	>0.25 NONE	NEG NONE		
	Debris	scalar scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water		*Visual	>0.25	NEG		
ELUD CONDITION							
FLUID CONDITION	Sodium	ppm	ASTM D5185m		<1		
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m		3		
	Barium	ppm	ASTM D5185m		2		
	Molybdenum	ppm	ASTM D5185m	12	<1		
	Manganese Magnesium	ppm	ASTM D5185m ASTM D5185m	12	2 1		
	Calcium	ppm	ASTM D5185m		71		
	Phosphorus	ppm	ASTM D5185m		313		
	Zinc	ppm	ASTM D5185m		50		
	Sulfur	ppm	ASTM D5185m		15232		
	Visc @ 40°C	cSt	ASTM D445		173		
Papart Id: PIPTAM (MILISCAPI 05210484 (Caparatad: 05/22/2024 04:20:02) Pay: 1					otion: DODE		





Certificate L2367

Laboratory Sample No.

: VCP443017 Lab Number : 06210484 Unique Number : 11083348 Test Package : MOB 1

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 14 Jun 2024 **Tested** : 18 Jun 2024

Diagnosed : 18 Jun 2024 - Sean Felton

Contact: ROBERT TURNER rturner@ripatampa.com

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Contact/Location: ROBERT TURNER - RIPTAM

TAMPA, FL

US 33619

T:

F:

RIPA AND ASSOCIATES

10149 FISHER AVENUE